

Stock 86937

Customer Copy
**Repair Order
 Invoice**

Date	Invoice	A/C	Customer PO	Page
Feb 21, 2017	WI013259	1317		1 / 6

RO WO014020

WO Date Dec 30, 2016

VIN 1XKDD9X52J894905	License AG50133	Last Cert. ()
Make KENWORTH	Model T800	Year 2002
Engine 6NZ61736	ODOMETER 1197 MI	

Activity Description	Part Number	Part Description	Quantity	Charge	Total
1. PASI Semi Annual			1.00 HR	81.0000	81.00
<i>PA Annual State Inspection Sticker: A17030996 2/2018 Tires: 17 Brakes: LF:7R LR: 9R RF: 7R RR:9R</i>					
				Activity Sub-total:	81.00
2. F/S Full Service			4.00 HR	81.0000	324.00
<i>Full Service</i>					
	DONP554005	OIL FILTER	1.00 EA	12.7600	12.76
	DONP551311	FUEL FILTER	1.00 EA	8.9500	8.95
	P551034	FILTER FUEL	1.00 EA	22.6700	22.67
	G36109	CHEVRON DELO 15W40 - *257004-981*	44.00 QT	2.2933	100.91
				Activity Sub-total:	469.29

Repair Order Invoice

Date	Invoice	A/C	Customer PO	Page
Feb 21, 2017	WI013259	1317		2 / 6
Activity Description				
Part Number	Part Description	Quantity	Charge	Total
3. INFRAME OVERHAUL - WAS PUSHING COOLANT		60.00 HR	81.0000	4,860.00
<i>Inframe Overhaul - Inspected truck for pushing coolant determined it was getting compression in the cooling system, removed cylinder head found gasket blown between 4 & 5 cylinders. checked liner heights, heights are low, cylinder liners were worn, decided to inframe engine</i>				
RC1030	RAD CAP 10LB	1.00 EA	7.7400	7.74
G29005	(07447) GEN RED SCOTCH PAD	1.00 EA	1.1095	1.11
G36074	BRAKE CLEANER *4620PEN*	2.00 EA	2.1100	4.22
1214283	DIPSTICK	1.00 EA	45.2800	45.28
1241855	HEAD BOLT 12PT	5.00 EA	13.8500	69.25
10R9347	ENGINE KIT	1.00 EA	10,066.97	10,066.97
10R9347-C1	CORE ENGINE KIT	1.00 EA	6,742.970	6,742.97
10R9347-C1	CORE ENGINE KIT	-1.00 EA	6,742.970	-6,742.97
20R3318	ROCKER ARM	6.00 EA	101.7900	610.74
20R3318-C1	CORE ROCKER	6.00 EA	55.3700	332.22
20R3318-C1	CORE ROCKER	-6.00 EA	55.3700	-332.22
20R3322	ARM ROCKER INJECTOR	6.00 EA	171.1600	1,026.96
20R3322-C1	CORE ROCKER	6.00 EA	93.0900	558.54
20R3322-C1	CORE ROCKER	-6.00 EA	93.0900	-558.54
10R3292	CAMSHAFT	1.00 EA	947.6600	947.66
10R3292-C1	CORE CAMSHAFT	1.00 EA	638.1600	638.16
10R3292-C1	CORE CAMSHAFT	-1.00 EA	638.1600	-638.16
177148BWT	TURBOCHARGER NEW	1.00 EA	1,795.130	1,795.13
1656170	PLUG ENGINE BLOCK	3.00 EA	5.6800	17.04
1029089	CAM COVER	1.00 EA	13.8700	13.87
20R3320	ROCKER ARM EXH/INT	6.00 EA	116.2800	697.68
20R3320-C1	CORE ROCKER	6.00 EA	63.2500	379.50
20R3320-C1	CORE ROCKER	-6.00 EA	63.2500	-379.50
1891814	KIT COOLER	1.00 EA	125.6500	125.65

Repair Order Invoice

Date	Invoice	A/C	Customer PO	Page	
Feb 21, 2017	WI013259	1317		3 / 6	
Activity Description					
Part Number	Part Description	Quantity	Charge	Total	
DONP153551	AIR FILTER	1.00 EA	39.1800	39.18	
G36074	BRAKE CLEANER *4620PEN*	6.00 EA	2.6900	16.14	
G29040	3/4 BRUSH *61CY72*	1.00 EA	14.7187	14.72	
G36123	24200 THREADLOCKER BLUE (765-1140) *24200PTX*	1.00 EA	3.8500	3.85	
G29632	07480 2" CLEANING DISC	3.00 EA	1.2832	3.85	
G29043	1/4 BRUSH *61CY71*	1.00 EA	8.0950	8.10	
4589587	CAT YELLOW	2.00 EA	8.8700	17.74	
1497378	GROMMET	18.00 EA	4.1800	75.24	
K269-261	FREON COMP BRKT	1.00 EA	164.3500	164.35	
7W3580	BRACKET	1.00 EA	77.1500	77.15	
4P2383	ADAPTER	1.00 EA	110.9400	110.94	
860-5556	BLOCK HEATER	1.00 EA	53.9900	53.99	
1212	BLOCK HTR PLUG	1.00 EA	20.4500	20.45	
1612	CAP BLOCK HEATER PLUG	1.00 EA	24.8000	24.80	
G09171	D2115-4436 #8 MALE JIC-#8 O-RING	1.00 EA	1.6300	1.63	
1396	2" DISC 50 GRIT	4.00 EA	1.4272	5.71	
1330125CAT	OIL COOLER CATERPILLAR	1.00 EA	374.7700	374.77	
1241854	HEAD BOLT	1.00 EA	15.2500	15.25	
5/16X18	HELICOIL	1.00 EA	0.6150	0.62	
G40067	3/8 SILICONE HOSE *D1029-2932*	3.00 EA	4.7800	14.34	
G40083	9206TRP SIL HOSE CLAMP	1.00 EA	1.1000	1.10	
CT5512	CABLE TIE	18.00 EA	0.2000	3.60	
1552270	PLUG KIT	2.00 EA	2.9400	5.88	
CT5317	CABLE TIE	16.00 EA	0.1100	1.76	
9X3402	ECM TERMINAL	4.00 EA	1.3300	5.32	
EC3555	COOLANT EXT LIFE	9.00 GA	8.9583	80.62	
G16225	727648 3/16 HEAT SHRINK	1.00 EA	0.7883	0.79	
1261768	TERMINAL	4.00 EA	1.5600	6.24	

Repair Order Invoice

Date	Invoice	A/C	Customer PO	Page	
Feb 21, 2017	WI013259	1317		4 / 6	
Activity Description	Part Number	Part Description	Quantity	Charge	Total
				Activity Sub-total:	21,437.43
4. GRINDING NOISE COMING FROM TRANSMISSION			6.00 HR	81.0000	486.00
<i>pulled truck into shop, run and found noise coming from R PTO - removed R PTO found bearings and gears trashed- Removed L PTO and removed bearing material from trans also found L PTO damaged installed new PTO's</i>					
	G29660	3M 07481 ROLOC CLEANING DISC ALUM	1.00 EA	1.2832	1.28
	660XQAHX-V3XD	PTO MODEL 660	1.00 EA	748.5600	748.56
	489GSAHX-A3XD	489 PTO	1.00 EA	539.3500	539.35
				Activity Sub-total:	1,775.19
5. TOWING			1.00 HR	450.0000	450.00
<i>Cocker towed truck 75 down to Norrisville Road White Hall MD & pu 77 and brought back to shop</i>					
				Activity Sub-total:	450.00
6. ROOTS MACHINE SHOP			1.00 HR	1,542.000	1,542.00
<i>Roots Machine Shop - Bore & install 1st waterhole insert Machine counterbores for .0324 shims</i>					
				Activity Sub-total:	1,542.00
7. RESEAL OIL FILTER BASE & OIL COOLER			4.20 HR	81.0000	340.20
<i>Reseal Oil filter base & Oil Cooler</i>					
				Activity Sub-total:	340.20

Repair Order Invoice

C

Date	Invoice	A/C	Customer PO	Page	
Feb 21, 2017	WI013259	1317		5 / 6	
Activity Description	Part Number	Part Description	Quantity	Charge	Total
8. R & R CAC			3.60 HR	81.0000	291.60
<i>R & R CAC</i>					
	GD11350	DRIER	1.00 EA	24.0300	24.03
	D9013-3307	AC LINE COND TO COMP	1.00 EA	187.2500	187.25
	A	MISC. NUT/BOLT/WASHER	1.00 EA	0.3850	0.39
	B	MISC. NUT/BOLT/WASHER	3.00 EA	0.1200	0.36
	J19958	CAC	1.00 EA	592.5000	592.50
	C	MISC. NUT/BOLT/WASHER	2.00 EA	0.2550	0.51
	P14362-028	CLAMP LINED 3/4"	2.00 EA	0.9500	1.90
	P554685	COOLANT FILT	1.00 EA	6.2700	6.27
	15-740	BOOT 7 WAY *PHI15-740*	1.00 EA	1.2000	1.20
	G40010	D2006-2255 # 24 CLAMP	1.00 EA	0.8600	0.86
				Activity Sub-total:	1,106.87
9. R & R WIPER BLADES			0.40 HR	81.0000	32.40
<i>R & R Wipers as needed</i>					
	57-18	BLADE WIPER *HLK8318HB* *WCS18-10*	2.00 EA	11.2600	22.52
				Activity Sub-total:	54.92
10 KENWORTH-PROGRAM ECM			1.00 HR	764.0000	764.00
<i>Program ECM</i>					
				Activity Sub-total:	764.00

Repair Order Invoice

Date	Invoice	A/C	Customer PO	Page
Feb 21, 2017	WI013259	1317		6 / 6
Activity Description				
Part Number	Part Description	Quantity	Charge	Total
	11 LEFT MUD FLAP FALLING OUT	0.20 HR	81.0000	16.20
	<i>Re install left mud flap into bracket correctly.</i>			
1075769	O-RING	1.00 EA	4.6900	4.69
			Activity Sub-total:	20.89

Technician 5-Jayson D
4-Volodymyr
8-Colby

Authorized

Total Labor:	9,187.40
Total Parts:	18,854.39
Shop Supplies:	0.00
SubTotal:	28,041.79
INVOICE TOTAL:	28,041.79

----Thank you for your business!
Please pay from invoice.
Remit payment to new address as shown!
1.5% Finance Charge will be added after 30 days (18% Annual)
ALL RETURNS REQUIRE PREVIOUS AUTHORIZATION OR YOU WILL NOT RECEIVE CREDIT! (FREIGHT IS NOT-CREDITABLE)
ALL PARTS SUBJECT TO RESTOCKING FEE. ABSOLUTELY NO RETURNS ON SPECIAL ORDER PARTS!
www.goodtransportservices.com

Signature: _____