



805 Vogelsong Road  
York, PA 17404  
Phone: (717) 848-8797  
Fax: (717) 848-2357

REMIT TO:  
KENWORTH OF PENNSYLVANIA  
4909 Louise Drive Suite 105  
Mechanicsburg, PA 17055

Customer:  
166960

Ship To:

REPRINT CUSTOMER  
INVOICE  
Work Order  
YS8007

Invoice Date: 10-14-22

Tax ID:

Tax ID Date: 07-09-19

Page 1 of 4

Page 1 of 4

Year	Make / Model	VIN	License	Mileage	Unit / Stock	Authorization
2019	KENWORTH / T680	1XKYDP9X5KJ293802	AG59355 PA	542489	146379	
Open Date / Time	Delivery Date	Delivery Mileage	Engine Hours	Reefer Hours	Standby Hours	P.O. Number
09-09-22 / 08:58AM	12-07-18		13277.0			
Complete	Engine Model / Serial #	Transmission Model/Serial #			Key Tag	Service Writer
10-13-22	MX-13 / Y178291	FULLER RTLO18918B 18-SPEED SUPE / K1301950				JB*JB
Memo						

- 1 PRESSURE IN COOLING SYSTEM - CUSTOMER STATES THE UNIT HAS PRESSURE BUILDING IN THE COOLING SYSTEM. CHECK AND ADVISE.

CAUSE:

FAILED HEAD GASKET ALLOWING PRESSURE TO BUILD IN THE COOLING SYSTEM.

CORRECTION:

WARMED ENGINE AND PERFORMED A COMBUSTION GAS TEST ON THE COOLING SYSTEM. UNIT TESTED POSITIVE FOR COMBUSTION GASSED IN THE COOLING SYSTEM.

TOTAL LABOR

510.00

TOTAL PARTS

16.71

Qty	Part Number	Description	List	Unit	Extended
1	PB16	BLASTER	12.25	6.81	6.81
2	4620PEN	CLEANER-N	6.19	4.95	9.90

- 2 IN FRAME OVERHAUL - PERFORM IN FRAME OVERHAUL DUE TO BROKEN HEAD BOLT AND FAILED HEAD GASKET.

CAUSE:

HEAD GASKET FAILED DUE TO BROKEN HEAD BOLT AND LINER FRETTING.

CORRECTION:

DRAIN ALL FLUIDS, REMOVE AIR CLEANER, CAC PIPES, UPPER RAD PIPE, FUEL LINES FROM BACK OF HEAD, VALVE COVER, VALVE TRAIN, INJECTORS (BAG AND LABEL FOR REUSE), EGR COOLER (TESTED ONCE REMOVED; OKAY FOR REUSE), TURBO. REMOVE CYLINDER HEAD, OIL PAN, FIXING FRAME, OIL PUMP AND PICKUP, RODS AND PISTONS, AND LINERS. WRAP ROD JOURNALS OF CRANKSHAFT. CLEAN BLOCK DECK WITH WET STONE. HEAD WILL NEED REPLACED DUE TO CRACKING IN BETWEEN VALVES. CUT COUNTERBORES TO ACHIEVE CORRECT LINER PROTRUSION. INSTALL NEW LINERS, REUSE RODS, INSTALL NEW PISTON SETS, ROD AND MAIN BEARINGS; TORQUE TO MX SPEC. INSTALL NEW OIL PUMP, FIXING FRAME, OIL PICKUP; TORQUE ALL TO MX SPEC. INSTALL NEW SERVICE HEAD GASKET, NEW HEAD; TORQUE TO MX SPEC AND SEQUENCE. RESEAL INJECTORS, INSTALL TO ORIGINAL LOCATIONS, NEW FUEL LINES TO INJECTORS, PUSH RODS, VALVE ROCKERS; TORQUE ALL TO MX SPEC AND SEQUENCE. SET OVERHEAD ADJUSTMENT. INSTALL NEW VALVE COVER SEALS. ATTACH ALL FUEL AND COOLANT

Terms: Net 10th E.O.M The dealer expressly disclaims all warranties, express or implied, including any implied warranties of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any person to assume for it any liability in connection with the sale of these parts and/or service. Damages - Buyer shall not be entitled to recover from dealer any consequential damages, damages to property, for loss of use, time, profits, or income, or any other incidental damages. Dealer not responsible for items left in vehicles.

RECEIVED BY: \_\_\_\_\_ DATE: \_\_\_\_\_

MOTOR TRUCK EQUIPMENT COMPANY - SINCE 1933

CARLISLE • NEW STANTON • DUNMORE • CLINTONVILLE • SHARTLESVILLE • YORK • LANCASTER • PITTSBURGH



**Work Order**

**YS8007**

Page 3 of 4

Invoice Date: 10-14-22

Page 3 of 4

Year	Make / Model	VIN	License	Mileage	Unit / Stock	Authorization
2019	KENWORTH / T680	1XKYDP9X5KJ293802	AG59355 PA	542489	146379	
Open Date / Time	Delivery Date	Delivery Mileage	Engine Hours	Reefer Hours	Standby Hours	P.O. Number
09-09-22 / 08:58AM	12-07-18		13277.0			
Complete	Engine Model / Serial #	Transmission Model/Serial #			Key Tag	Service Writer
10-13-22	MX-13 / Y178291	FULLER RTLO18918B 18-SPEED SUPE / K1301950				JB*JB
Memo						

1	2106210PE	GASKET- T	25.18	17.17	17.17
4	1895972PE	BOLT-FLAN	19.71	17.34	69.36
2	1844625PE	RING-SEAL	1.50	1.02	2.04
4	2116602PE	O-RING, 7	5.56	3.78	15.12
1	1979191PE	V-CLAMP,	57.23	39.00	39.00
1	2035973PE	GASKET-EX	34.93	23.81	23.81
1	1923003PE	GASKET	14.44	9.83	9.83
2	1930520PE	PIPE-FUEL	238.39	162.46	324.92
1	P550851	FILTER-FU	40.52	27.55	27.55
1	2011888PE	SCREW CAP	199.55	135.99	135.99
7	1822941PE	BOLT-FLAN	5.15	4.53	31.71
1	2130588PE	O-RING, 1	7.58	5.16	5.16
1	2176771PE	GASKET SE	849.45	578.90	578.90
7	2239664PE	BEARING S	30.66	20.89	146.23
7	2239665PE	BEARING S	28.56	19.46	136.22
4	1736755PE	WASHER-TH	11.15	9.81	39.24
6	2132582PE	PISTON, W	874.03	595.65	3,573.90
6	1858819PE	BEARING S	49.93	34.03	204.18
6	1655712PE	BEARING S	49.93	34.03	204.18
1	2136411PE	O-RING	3.25	2.22	2.22
1	2267065PE	COOLANT P	1,231.76	839.44	839.44
1	2294074PE	OIL PUMP	921.66	628.11	628.11
1	2140216PE	AIR BREAT	63.56	43.32	43.32
12	1878508PE	BOLT-CONN	2.59	2.28	27.36
4	2047593PE	PIPE-FUEL	248.32	169.22	676.88
1	2013452PE	HOLDER-CO	100.21	68.29	68.29
6	1982746PE	CYLINDER	370.15	252.26	1,513.56
2	4620PEN	CLEANER-N	6.19	4.95	9.90
1	2188417PEX	CYLINDER	8,067.53	5,498.02	5,498.02
1	4620PEN	CLEANER-N	6.19	4.95	4.95
1	2180879PE	COOLANT T	72.29	46.92	46.92
2	DC4016023	GREASE-MO	65.06	48.80	97.60
12	1603978PE	O-RING, C	23.20	15.82	189.84
1	3163087	LUBRICANT	39.31	28.26	28.26
1	2106218PE	GASKET-CO	12.92	8.80	8.80
1	2007405PE	O-RING, 8	4.53	3.09	3.09
1	P621725	PACCAR AI	217.03	156.26	156.26
14	1822165PE	BOLT-COVE	5.99	5.27	73.78
-15	KW COUPON	Y223197	1.00	1.00	-15.00

3 COOLANT LINES - FOUND COOLANT LINES AT DAVCO FUEL FILTER ARE LEAKING AND NEED REPLACED.

CAUSE:

DAVCO FUEL FILTER COOLANT LINES LEAKING AFTER OVERHAUL.

CORRECTION:

DRAINED COOLANT AND REPLACED THE DAVCO FUEL FILTER COOLANT LINES.

Terms: Net 10th E.O.M The dealer expressly disclaims all warranties, express or implied, including any implied warranties of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any person to assume for it any liability in connection with the sale of these parts and/or service. Damages - Buyer shall not be entitled to recover from dealer any consequential damages, damages to property, for loss of use, time, profits, or income, or any other incidental damages. Dealer not responsible for items left in vehicles.

RECEIVED BY: \_\_\_\_\_ DATE: \_\_\_\_\_

**MOTOR TRUCK EQUIPMENT COMPANY - SINCE 1933**

CARLISLE • NEW STANTON • DUNMORE • CLINTONVILLE • SHARTLESVILLE • YORK • LANCASTER • PITTSBURGH

**Work Order**

**YS8007**

Invoice Date: 10-14-22

Page 4 of 4

Page 4 of 4

Year	Make / Model	VIN	License	Mileage	Unit / Stock	Authorization
2019	KENWORTH / T680	1XKYDP9X5KJ293802	AG59355 PA	542489	146379	
Open Date / Time	Delivery Date	Delivery Mileage	Engine Hours	Reefer Hours	Standby Hours	P.O. Number
09-09-22 / 08:58AM	12-07-18		13277.0			
Complete	Engine Model / Serial #	Transmission Model/Serial #			Key Tag	Service Writer
10-13-22	MX-13 / Y178291	FULLER RTLO18918B 18-SPEED SUPE / K1301950				JB*JB
Memo						

REFILLED COOLANT.

TOTAL LABOR	425.00
TOTAL PARTS	316.60

Qty	Part Number	Description	List	Unit	Extended
1	F50-2089	HOSE-ASSY	90.45	80.50	80.50
1	F50-2090	HOSE-ASSY	149.17	125.30	125.30
2	7006473500	FITTING	65.95	55.40	110.80
SHOP SUPPLIES					500.00

	OTH SUPL RECOVERY-YK	0610821	500.00
	ACCTS REC-COUPONS-YK	2200800	-15.00
	RETAIL LBR TRK-YK	4610840	11,203.00
	P&A RETAIL RO'S-YK	4680800	19,099.22
166960	CHARGE	2200000	30,787.22

Terms: Net 10th E.O.M The dealer expressly disclaims all warranties, express or implied, including any implied warranties of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any person to assume for it any liability in connection with the sale of these parts and/or service. Damages – Buyer shall not be entitled to recover from dealer any consequential damages, damages to property, for loss of use, time, profits, or income, or any other incidental damages. Dealer not responsible for items left in vehicles.

RECEIVED BY: \_\_\_\_\_ DATE: \_\_\_\_\_

**MOTOR TRUCK EQUIPMENT COMPANY – SINCE 1933**  
**CARLISLE • NEW STANTON • DUNMORE • CLINTONVILLE • SHARTLESVILLE • YORK • LANCASTER • PITTSBURGH**