

67 Neville Avenue McKees Rocks, PA. 15136 Phone: (412) 778-0160

Fax: (412) 778-0170

REMIT TO: KENWORTH OF PENNSYLVANIA 4909 Louise Drive Suite 105 Mechanicsburg, PA 17055



How Did We Do?

Customer: 30091

_.... . . JH

Ship To: .

ρ

REPRINT CUSTOMER INVOICE **Work Order** MS13674

Invoice Date: 05-24-24

Tax ID:

Tax ID Date:

Page 1 of 4

| Year | Make / Model | | VII | N License | | Mileage | Unit / Stock | Authorization | | |
|----------|--------------|-------------------|----------|-------------|----------|-----------|--------------|---------------|---------------|----------------|
| 2014 | Pet | erbilt / 388 | | 1NPWLP0X0ED | | 5 451436N | | 54 | | |
| Open | Date / Time | Delivery Date | Delivery | y Mileage | Engine I | lours | Reef | fer Hours | Standby Hours | P.O. Number |
| 03-12- | 24 / 04:04PM | 03-27-13 | | | 1667 | 7.0 | | 0.0 | 0.0 | |
| Complete | e En | gine Model / Seri | ial # | | Transn | nission N | /lodel/ | Serial # | Key Tag | Service Writer |
| 05-23-24 | | MX-13 / | | | | Fulle | er/ | | | DN*SRO |
| Memo | | | | | | | | | | |

1 PULL HEAD AND INSPECT

REMOVE ALL ACCESS ITEMS TO REMOVE HEAD, INCLUDING CLEAN AIR PIPING, WIRING HARNESSES, EXHAUST COMPONENTS, INTAKE HORN, CAC PIPING, VALVE COVER, ROCKER HOUSING AND ASSEMBLIES. REMOVE CYLINDER HEAD AND INSPECT FOR DAMAGE. PRESSURE TEST CYLINDER HEAD. MEASURE CYLINDER LINER PROTRUSION, FOUND TO BE LOW. ENGINE BLOCK COUNTER BORES NEED CUT.

> TOTAL LABOR TOTAL PARTS

1,512.00

62.54

Oty Part Number -----

Description

Unit Extended

1 1204090105

CLEANING SOLUTION-EGR (GA

62.54

62.54

2 FAN HUB ISSUE

CHECKED THE FAN HUB. UNBOLTED THE FAN BLADE FROM THE HUB AND PUSHED INTO THE SHROUD. FOUND 2 BROKEN HUB MOUNTING BOLTS, 1 LOOSE AND 1 THAT LOOKS LIKE IT WAS NEVER IN. PULLED THE HUB OUT FROM ENGINE. WAS ABLE TO USE VICE GRIPS AND PULL OUT ONE OF THE BROKEN BOLTS. OTHER ONE IS BROKEN FLUSH WITH BLOCK. CLEANED THE BOLT HEAD AND WELDED A NUT TO THE BROKEN BOLT. PULLED OUT THE BROKEN BOLT. RAN A TAP THROUGH ALL THE MOUNTING HOLES AND GOT THE CORRECT BOLT LENGTH FOR NEW ONES. PULLED OUT THE BROKEN FAN BLADE AND SET THE NEW BLADE IN THE SHROUD TO INSTALL LATER. INSTALLED THE FAN HUB WITH NEW BOLTS AND LOCTITE. TIGHTENED DOWN.

> TOTAL LABOR TOTAL PARTS

472.50

381.22

Qty Part Number Description Unit Extended _____ BLADE-FAN*813*CW SUCKER,9 1 996813502-002 274.14 274.14 1 D84-1002-121866 BELT-ENGI 107.08

3 INFRAME QUOTE PERFORM ENGINE OVERHAUL

Terms: Net 10th E.O.M The dealer expressly disclaims all warranties, express or implied, including any implied warranties of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any person to assume for it any liability in connection with the sale of these parts and/or service. Damages - Buyer shall not be entitled to recover from dealer any consequential damages, damages to property, for loss of use, time, profits, or income, or any other incidental damages. Dealer not responsible for items left in vehicles.

| RECEIVED BY: | DATE: |
|--------------|-------|
| RECEIVED DT: | DAIC. |
| | |

MS13674

| Year | Make / Model | | VIIV | 1 | Lice | nse | Mileage | Unit / Stock | Authorization | |
|----------|--------------|-------------------|-----------|---------|------------------|-----------|---------|--------------|---------------|----------------|
| 2014 | Pet | erbilt / 388 | 1NPWLP0X0 | | NPWLP0X0ED214695 | | | 451436M | 54 | |
| Open I | Date / Time | Delivery Date | Delivery | Mileage | Engine H | lours | Ree | fer Hours | Standby Hours | P.O. Number |
| 03-12-2 | 24 / 04:04PM | 03-27-13 | | | 16677 | '.O | | 0.0 | 0.0 | |
| Complete | e En | gine Model / Seri | ial # | | Transn | nission N | /lodel/ | Serial # | Key Tag | Service Writer |
| 05-23-24 | | MX-13 / | | | | Fulle | er/ | | | DN*SRO |
| Memo | | | | | | | | | | |

- DRAIN ENGINE OIL, REMOVE OIL PAN, OIL PICKUP TUBE, AND STIFFENER PLATE.
- REMOVE RODS AND PISTONS
- REMOVE ALL 6 CYLINDER LINERS
- CLEAN BLOCK DECK AND SET UP FOR COUNTER BORE MACHINING.
- PERFORM COUNTER BORE MACHINING TO ALL 6 CYLINDERS
- CLEAN BLOCK FROM MACHINING
- INSTALL NEW CYLINDER LINERS WITH NEW O-RINGS
- REMOVE AND REPLACE ALL MAIN BEARINGS AND TORQUE TO SPEC.
- INSTALL NEW PISTONS ON RODS
- INSTALL ROD ASSEMBLIES WITH NEW BEARING AND TORQUE TO SPEC.
- INSTALL NEW HEAD GASKET
- INSTALL NEW CYLINDER HEAD AND HEAD BOLTS, TORQUE TO SPEC.
- INSTALL FUEL INJECTORS WITH NEW BOLTS, O-RINGS, AND SEALS.
- INSTALL NEW FUEL SUPPLY LINES.
- INSTALL ROCKER ASSEMBLIES AND ADJUST OVERHEAD.
- INSTALL ROCKER HOUSING.
- INSTALL EXHUAST MANIFOLD WITH NEW GASKETS
- INSTALL TURBO, EGR COOLER, EGR VALVE AND PIPING.
- INSTALL INTAKE HORN.
- INSTALL CHARGE AIR PIPING
- INSTALL COOLANT PIPING
- INSTALL WIRING HARNESSES
- INSTALL FUEL FILTER HOUSING AND LOW PRESSURE LINES.
- INSTALL STIFFENER PLATE
- INSTALL OIL PICKUP AND OIL PAN WITH NEW GASKET.
- INSTALL VALVE COVER- INSTALL CLEAN AIR PIPING.
- FILL ENGINE WITH NEW OIL AND REPLACE FILTERS
- FILL COOLING SYSTEM WITH NEW COOLANT.
- CHARGE BATTERIES
- RUN ENGINE AND CHECK FOR LEAKS, CHEKCS OKAY
- PERFORM ROAD TEST, CHECKS OKAY.

TOTAL LABOR
TOTAL PARTS

9,828.00 18,208.74

| Qty | Part Number | Description | Unit | Extended |
|-----|-------------|---------------------------|----------|----------|
| 1 | 2299987PE | OVERHAUL | 5,318.52 | 5,318.52 |
| 1 | 1933207PEX | EGR COOLE | 2,173.63 | 2,173.63 |
| 6 | 1313120PE | BOLT-FLANGE M8X55 | 0.61 | 3.66 |
| 6 | CH498745-14 | BRAKE CLEANER NON-CL 48 S | 5.94 | 35.64 |
| 2 | 105FBC | GREASE-MOTOR ASSY 10 OZ L | 11.15 | 22.30 |
| 1 | 3164067CUM | SEALANT | 28.03 | 28.03 |
| 1 | KEE | STARTING FLUID | 8.50 | 8.50 |
| 1 | 1805233PE | GASKET-EXHAUST TURBOCHARG | 24.33 | 24.33 |
| 1 | 1791610PE | O-RING | 26.45 | 26,45 |

Terms: Net 10th E.O.M The dealer expressly disclaims all warranties, express or implied, including any implied warranties of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any person to assume for it any liability in connection with the sale of these parts and/or service. Damages – Buyer shall not be entitled to recover from dealer any consequential damages, damages to property, for loss of use, time, profits, or income, or any other incidental damages. Dealer not responsible for items left in vehicles.

| RECEIVED BY: | DATE: |
|--------------|-------|

| | | | | | | | | | | Т |
|---|---|---|---|---|---|---|---|---|---|---|
| ١ | V | ! | ς | 1 | l | 3 | 6 | 7 | 4 | Ļ |

| Year | Make / Model | | | VIN | VIN License | | Mileage | Unit / Stock | Authorization | |
|----------|----------------------|--------------------|------------|----------------------|-------------|----------|----------|--------------|---------------|----------------|
| 2014 | Peterbilt / 388 1NPW | | IPWLP0X0 | P0X0ED214695 451436M | | 54 | | | | |
| Open | Date / Time | Delivery Date | Delivery N | Mileage | Engine H | lours | Reef | er Hours | Standby Hours | P.O. Number |
| 03-12-2 | 24 / 04:04PM | 03-27-13 | | | 16677 | .0 | | 0.0 | 0.0 | |
| Complete | e Er | igine Model / Seri | ial# | | Transm | ission N | /lodel/S | Serial # | Key Tag | Service Writer |
| 05-23-24 | | MX-13 / | | | | Fulle | er/ | | | DN*SRO |
| Memo | | | | | Ý | 1 | | | | |

| | | VI | | |
|----|--------------------------|---------------------------|--------|-----------------|
| 1 | 1791611PE | O RING | 26.04 | 26.04 |
| 4 | 0322364PE | RING-COPPER 16.2X21.9X1.3 | 0.97 | 3.88 |
| 10 | 0322364PE CH498745-14 | BRAKE CLEANER NON-CL 48 S | 5.94 | 59.40 |
| 2 | 1858036PE | RING-SEAL, 15X24X1.5 | 1.79 | 3.58 |
| 2 | 1976452PE | V-CLAMP, D=93.8 | 57.14 | 114.28 |
| 1 | 0507207PE | COUPLING- | 4.06 | 4.06 |
| 1 | 1816191PE | PIPE-COMPRESSOR | 78.23 | 78.23 |
| 2 | 1786103PE | GASKET-AIR INLET | 20.11 | 40.22 |
| 1 | 1439888PE | CONNECTOR | | 10.82 |
| 4 | 1844625PE | RING-SEALING 22.0X13.0X1. | | 5.80 |
| 1 | 1781938PE | HOSE-COMPRESSOR COOLANT R | | |
| 1 | 1904646PE | FUEL PIPE ASSEMBLY-HIGH P | 247.59 | 247.59 |
| 1 | FS19765FLG | SEPERATOR-FUEL FILTER | 36.17 | 36 .1 7 |
| 1 | 2267642PE | BANJO BOL | 4.22 | 4.22 |
| 1 | 1912684PE | VALVE-NON | | 81.32 |
| 1 | 1827519PE | GASKET-EXHAUST FLEX TURBO | 36.69 | 36.69 |
| 12 | EC3501 | COOLANT-TRP ELC 50/50 JUG | 9.22 | 36.69 110.64 |
| 1 | M1N15 | FUSE-15 AMP | 1.66 | 1.66 |
| 1 | M1N10 | FUSE-10 AMP(5EA=1BOX) | 1.66 | 1.66 |
| 3 | 1787297PE | CLIP-PIPE/HOSE | 33.87 | 101.61 |
| 10 | CH498745-14 | BRAKE CLEANER NON-CL 48 S | 5.94 | 59.40 |
| 3 | CH498745-14 | BRAKE CLEANER NON-CL 48 S | 5.94 | 17.82 |
| 1 | 2866337CUM | GASKET, AFM DEVICE | 16.20 | 16.20 |
| 1 | 90-0013 | CLAMP-V BAND 5" | 14.95 | 14.95 |
| 1 | 2880215CUM | GASKET, AFM DEVICE | 21.03 | 21.03 |
| 1 | 2880213CUM | CLAMP, V BAND | | 66.56 |
| | 1904646PE | FUEL PIPE ASSEMBLY-HIGH P | | |
| 1 | 2190199PEX | CYLINDER | | 6,322.11 |
| 1 | 2144944PE | HARNESS-I | 221.61 | |
| 1 | CT9444TRP | CLAMP-CONSTANT TORQUE #44 | 9.98 | 9.98 |
| 1 | F16-6009031B413SB0 | CLAMP-HOSE T BOLT | 17.43 | 17.43 |
| 2 | CH498745-14 | BRAKE CLEANER NON-CL 48 S | 5 94 | 11 88 |
| | CT550LTRP | CLAMP-CONST TORQUE HD SS | 14.95 | 29.90 |
| 1 | 1827279PE | GASKET-EXHUAST | 38.56 | 38.56 |
| | 1827519PE | GASKET-EXHAUST FLEX TURBO | 36.69 | 36.69 |
| | 1782835PE | V-CLAMP, QUICK CONNECT | 35.00 | |
| | 1798862PE | CLAMP | 27.33 | |
| 6 | 1977900PE | CYLINDER | 270.99 | 1,625.94 |
| | | | | |

6 REPAIR ISSUES UNRELATED TO OVERHAUL

FOUND UNIT PUMP LEAKING EXTERNALLY. DISCONNECTED FUEL LINE. LOOSENED HOLD DOWN BOLTS. REMOVED UNIT PUMP. CLEANED RUST FROM PUMP MATING SUFACES. INSTALLED PUMP. INSTALLED FUEL LINE. PROGRAMED UNIT PUMP. NEW PUMP CODE: LJFM. CLEARED CODES. STARTED UNIT AND LET IDLE. CODE RETURNED. SWAP NUMBER 3 FUEL INJECTOR AND JAKE BRAKE ASSEMBLY TO VERIFY THE FAILED COMPONENT, FOUND FUEL INJECTOR TO BE FAILED. REMOVE

Terms: Net 10th E.O.M The dealer expressly disclaims all warranties, express or implied, including any implied warranties of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any person to assume for it any liability in connection with the sale of these parts and/or service. Damages – Buyer shall not be entitled to recover from dealer any consequential damages, damages to property, for loss of use, time, profits, or income, or any other incidental damages. Dealer not responsible for items left in vehicles.

| RECEIVED BY: | DATE: | |
|--------------|-------|--|

GASKET.

| | | | | | | | - | | oməM |
|----------------|--------------|------------|-------------|------------------|------------|--------|------------------|-----------|----------|
| DN*SRO | | | Fuller / | | | | / £I-XM | | ₽Z-8Z-S0 |
| Service Writer | Кеу Тав | erial # | 2\l9boM noi | ssimsns T | | al # | ine Model / Seri | gn3 | Complete |
| | 0.0 | 0.0 | | 0.77831 | | | 61-72-60 | M940:40 \ | 03-12-24 |
| P.O. Number | tandby Hours | er Hours S | rs Reef | uoH ənign∃ | 9geəliM yı | Delive | Delivery Date | emiT \ et | ed nago |
| | 7 S | M9EtTSt | | ED214695 | 1NPWLP0X0 | | erbilt / 388 | 199 | 2014 |
| Authorization | Unit / Stock | 9gs9liM | License | N | IIΛ | | ləboM \ əx | lsM | Year |

CHEKCS OKAY. FOUND EXHUDST LEAK AT DOC, REMOVE AND REPLACE CLAMP AND TEPLACE SENSOR, GET CUST APPROVAL TO REPLACE SENSOR, R&R SENSOR, INLET NOX SENSOR, GET CUST APPROVAL TO REPLACE SENSOR, R&R SENSOR, INLET NOX SENSOR, GET CUST APPROVAL TO REPLACE SENSOR, R&R SENSOR, GET CUST APPROVAL TO REPLACE SENSOR, GET CUST APPROVAL TO REPLACE SENSOR, GET CUST APPROVAL TO REPLACE CLAMP AND TOUR SENSOR, GET CUST APPROVAL TO REPLACE CLAMP AND TOUR SENSOR, GET CUST APPROVAL TO REPLACE CLAMP AND TOUR SENSOR, GET CUST APPROVAL TO REPLACE CLAMP AND TOUR SENSOR, GET CUST APPROVAL TO REPLACE CLAMP AND TOUR SENSOR, GET CUST APPROVAL TO REPLACE CLAMP AND TOUR SENSOR, GET COUR SENSOR

| 06 | 9.002 I | OLH SNBL RECOVERY-MK 061092 | |
|---------------|-----------|-----------------------------|--------------------|
| - | 3.002 | | |
| | , 001 | 331 14413 40113 | |
| 19.0 | 19.0 | BOLT-FLANGE M8X55 | 1 1313120PE |
| ⊅ 5.01 | 78.01 | RING SEAL, INJECTOR | I SISYSSIPE |
| 89.7 | 89.7 | O-RING INJECTOR | 1 1638270PE |
| ٤٢.٢ | ٤٢.٢ | O-RING INJECTOR | I 1638271PE |
| 74.71E,1 | 74.718,1 | INJECTOR, MX-13 EPA10 | I 1852900PEX |
| 48.2 | 71.1 | BOLT-FLANGE M10 | 7 T830688PE |
| 344,34 | 46.44E | FUEL PUMP, MX-13 EPA 10, | 1 1861200PRX |
| 66 . 7 | 66.7 | O-RING D=126.59 | 1 1044267PE |
| 70.675 | 70.675 | COOLANT PUMP CARTRIDGE, S | 1 1945298bE |
| 65.499 | 65.499 | SENSOR-NOX, BEFORE CATALY | I 1886156PEX |
| bebnetx3 | tinU | Description | ζτλ Part Number |
| 98 | 2,742,5 | STЯ A 9 | JATOT |
| 05 | 1,228. | LABOR | JATOT |

30091 CHARGE 5700000 31,394.86 BETAIL LBR TRK-MD 4610940 13,041.00 7010940 34,935.86

Terms: Net 10th E.O.M The dealer expressly disclaims all warranties, express or implied, including any implied warranties of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any person to assume for it any liability in connection with the sale of these parts and/or service. Damages – Buyer shall not be entitled to recover from dealer any consequential damages, damages to property, for loss of use, time, profits, or income, or any other incidental damages. Dealer not responsible for items left in vehicles.

