



Stock 87200  
Repair Order Detail

RO: 105-00047266 Status: CLOSED Repair Class: SRVC CENTRAL  
Shop: 105 KTI ROAD BREAKDOWN  
Unit: 2912 ISX15/500/18SP/4AXLE  
Domicile: KT300 Make: PETXX Repair Site: OUTSIDE COMP  
Cost Cntr: KT08 Model: 367-63 UNI Opened: 5/9/2017  
VIN: 1XPTP4EXXCD157987 In Service: 2/15/2012 Closed: 8/1/2017  
Completed: 8/1/2017  
Ecm meter: 338,558

Section: 1	Priority: 5	Complaint: NEEDS INSPEC	Rep Reason: BREAKDOWN
Component: 045		Cmp Descrip: Power Plant	
War Type: EXPIRED		Unit War: None	
V			
Comments: USING COOLANT WATER IS GETTING INTO CRANK CASE ROOT CAUSE OF FAILURE: COOLANT LOSS, LOW CYLINDER LINERS. FAILED FUEL PUMP & CAM. DAMAGED CRANKSHAFT & METAL THROUGHOUT LUBRICATION OIL SYSTEM. FOUND DAMAGE TO THE CYLINDER BLOCK. <b>REPLACED WITH RECON ENGINE ALSO REPLACED CLUTCH</b>			

Services				
Date	Description	Vendor	Charge	Total
6/30/2017	CUMMINS HOUSTON BRANCH INV #012-96103	Y	44318.91	44,318.91

Task Details

Section: 2	Priority: 5	Complaint: DBM WARRANTY	Rep Reason: WARR DBM
Component: WC0-045		Cmp Descrip: POWER PLANT	
War Type: POLICY ADJ		Unit War: None	
V			
Comments: THIS SECTION TO CREDIT SECTION ONE FOR POLICY			


Services				
Date	Description	Vendor	Charge	Total
6/30/2017	PART WARR CREDIT	Y	(15918.20)	(15,918.20)
6/30/2017	LABOR WARR CREDIT	Y	(1984.50)	(1,984.50)

Task Details



Stock 87200  
Repair Order Detail

Totals Repair Order 105-00047266	
US\$ - United States Dollars	
Total Parts Issued:	0.00
Total Labor Hours:	0.00
Total Part Charges:	0.00
Total Labor Charges:	0.00
Total Tax Charges:	0.00
Total Fee Charges:	0.00
Total Service Charges:	26,416.21
Repair Total:	26,416.21



Cost For Each Line Type

26,416.21 00.00

26,416.21

