

Stack 87144

Repair Order Detail

RO:

105-00053753

Status: **CLOSED** Repair Class:

SCHEDULED

Shop:

105

KTI ROAD BREAKDOWN

Unit:

2975

ISX15/500/18SP/4AXLE

Domicile: SYSTEM

Make:

PETXX

Cost Cntr: KT08

Model:

367-63 UNI

Year:

2013

VIN:

1XPTP4EXXDD192031

In

5/18/2012

Service:

Repair Site: FACILITY

Opened:

5/13/2022

Closed:

6/22/2022

Completed: 6/22/2022

Ecmmeter: 691,730

Section: 1

Priority: 5

Complaint:

BREAKDOWN

Rep Reason: BREAKDOWN

Component: 045

Cmp Descrip:

Power Plant

War Type:

EXPIRED

Unit War:

None

Comments:

CONCERN: COOLANT INTO COMBUSTION CAUSE: CYLINDER LINERS CORRECTION: ENGINE

OVERHAUL

Services

Description

Total

6/22/2022

Date

MTE INVOICE#CS66960

16859.07

Charge

16.859.07

Kenworth of Pa

Task Details

Totals Repair Order 105-00053753

US\$ - United States Dollars

Total Parts Issued:

0.00

Total Labor Hours:

0.00

Total Part Charges:

0.00

Total Labor Charges:

0.00 0.00

Total Tax Charges:

0.00

Total Fee Charges:

Total Service Charges:


16,859.07 16,859.07

Version: 24.10.3.231

Repair Total:

© 2015, 2025 Trimble Inc. All rights reserved. Unauthorized duplication, copying, or use prohibited. Page: 1 of 2






Cost For Each Line Type



16,859.07



Version: 24.10.3.231