

Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

White
Auction Date: 10/13
Stock Number: 70074
Lot Number: _____

HESS REPORT SHEET

*** ALL Trucks are For Sale AS IS, WHERE IS ***

*** This is NOT A WARRANTY! ***

547,793.3

Truck Type (Circle one) Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: _____

Year: 2016 Make: Freightliner Model: Cascadia Vin #: HR4023

Engine: Make: DET Model: P HP: P

Odometer Reading: 547795 ECM Reading: _____

| Task | Yes | No | Comments |
|---|-------------------------------------|-------------------------------------|-------------------------------------|
| Does the Truck Start? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | Jump Start: <u>YES</u> or <u>NO</u> |
| Does the motor idle and run normally? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | |
| Does the truck have the Emission Deleted? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | |
| Does the Transmission operate in all gears? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | |
| Does the Air load in normal time? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | |
| Are there any fluid leaks? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | OIL or COOLANT MAJOR or MINOR |
| Do you see coolant in the oil? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | |
| Is the oil pressure at idle within OEM specs? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | |
| Is blow-by present? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | MAJOR or MINOR |
| Do you see oil in the coolant? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | |
| Pressure check the cooling system | <input checked="" type="checkbox"/> | <input type="checkbox"/> | PASS or FAIL |
| Is the clutch in good operating condition? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | Rate (1-10): _____ |

Brake Lining: Front R: CAN'T SEE Tag Axle R: _____ L: _____ 1st Axle R: _____ L: _____ 2nd Axle R: _____ L: _____ CAN'T SEE

Tire Tread Percentage: Front RF 50% Tag Axle: _____ 1st Axle: 30% 2nd Axle: 30%

Comments:

Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10

Comments:

HOOD Damage + BUMPER.

Other Comments:

Inspector Print: BRANT

Date: 8-28-23

Inspector Signature: Joel Brant

*** This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way ***