

Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

Auction Date: 10/13

Stock Number: 70073

Lot Number: _____

HESS REPORT SHEET

*** ALL Trucks are For Sale AS IS, WHERE IS ***

*** This is NOT A WARRANTY! ***

629,377

Truck Type (Circle one): Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: _____

Year: 2016 Make: Freightliner Model: CASCADIA Vin #: HP6326

Engine: Make: DET Model: DD15 HP: 505

Odometer Reading: 629,379 ECM Reading: _____

Task	Yes	No	Comments
Does the Truck Start?	☒	☐	Jump Start: <u>YES</u> or <u>NO</u>
Does the motor idle and run normally?	☒	☐	
Does the truck have the Emission Deleted?	☐	☒	
Does the Transmission operate in all gears?	☒	☐	
Does the Air load in normal time?	☒	☐	
Are there any fluid leaks?	☒	☐	OIL or COOLANT MAJOR or MINOR
Do you see coolant in the oil?	☒	☐	
Is the oil pressure at idle within OEM specs?	☒	☐	
Is blow-by present?	☒	☐	MAJOR or MINOR
Do you see oil in the coolant?	☒	☐	
Pressure check the cooling system	☒	☐	PASS or FAIL
Is the clutch in good operating condition?	☒	☐	Rate (1-10): <u>4</u>

Brake Lining: Front R: DISC CAN'T SEE Tag Axle R: _____ L: _____ 1st Axle R: DISC CAN'T SEE (DISC) L: _____ 2nd Axle R: _____

Tire Tread Percentage: Front: RF-30% Tag Axle: _____ 1st Axle: 40% 2nd Axle: LRF > 90% RRF-40%
RF-10% RR-90%

Comments: SOME DRIVER SIDE SLEEPER DAMAGE

Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10
Comments: HOOD DAMAGE

Other Comments: BOTH AIR FOLLO, BEHIND BUNK ARE DAMAGE

Inspector Print: BRANT

Date: 8-28-23

Inspector Signature: Jack Brant

*** This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way ***