

Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

White
Auction Date: 10/13
Stock Number: 70076
Lot Number: _____

HESS REPORT SHEET

*** ALL Trucks are For Sale AS IS, WHERE IS ***

*** This is NOT A WARRANTY! ***

351,006.2

Truck Type (Circle one): Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: _____

Year: 2015 Make: Freightliner Model: Ascadia¹²⁵ Vin #: GG7896

Engine: Make: DET Model: DD15 HP: 505

Odometer Reading: 351,007

ECM Reading: _____

Task	Yes	No	Comments
Does the Truck Start?	☒	☐	Jump Start: <u>YES</u> or <u>NO</u>
Does the motor idle and run normally?	☒	☐	
Does the truck have the Emission Deleted?	☒	☒	
Does the Transmission operate in all gears?	☒	☐	
Does the Air load in normal time?	☒	☐	
Are there any fluid leaks?	☒	☐	<u>OIL or COOLANT</u> MAJOR or MINOR
Do you see coolant in the oil?	☒	☒	
Is the oil pressure at idle within OEM specs?	☒	☐	
Is blow-by present?	☒	☒	MAJOR or MINOR
Do you see oil in the coolant?	☒	☒	
Pressure check the cooling system	☒	☐	<u>PASS</u> or <u>FAIL</u>
Is the clutch in good operating condition?	☒	☐	Rate (1-10): _____ <u>Automatic</u>
<u>(DESC) CAN'T SEE</u> Brake Lining Front R: _____ Tag Axle R: _____ L: _____ 1 st Axle R: _____ L: _____ 2 nd Axle R: _____ <u>CAN'T SEE (DESC)</u>			
Tire Tread Percentage Front: <u>80%</u> Tag Axle: _____ 1 st Axle: <u>LFI 70%</u> 2 nd Axle: <u>LRI 80%</u> <u>RRI 50%</u>			
Comments: <u>RFI 70%</u> <u>RRI 30%</u> <u>LRI 80%</u> <u>RRI 50%</u>			
Cosmetic Condition: Rate 1 2 3 4 <u>5</u> 6 7 8 9 10			
Comments: _____			
Other Comments: _____			

Inspector Print: BRANT

Date: 8-22-23

Inspector Signature: Jack Brant

*** This report is performed as a guide for our buyers. This Report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way ***