

Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

HRU 17,755

HESS REPORT SHEET

*** ALL Trucks are For Sale AS IS, WHERE IS ***

*** This is NOT A WARRANTY! ***

Auction Date: 10/13
Stock Number: 70241
Lot Number: 73,131

Truck Type (Circle one): Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: _____

Year: 2013 Make: KALMAR Model: 4X2 Vin #: 000384

Engine: Make: CUMMINS Model: 6.7L HP: 250

Odometer Reading: 73,132 ECM Reading: _____

Task	Yes	No	Comments
Does the Truck Start?		X	Jump Start YES or NO <u>ETHER</u>
Does the motor idle and run normally?	X	X	
Does the truck have the Emission Deleted?	X	X	
Does the Transmission operate in all gears?	X	X	
Does the Air load in normal time?	X	X	
Are there any fluid leaks?	X	X	OIL or COOLANT MAJOR or MINOR <u>MINOR</u>
Do you see coolant in the oil?	X	X	
Is the oil pressure at idle within OEM specs?	X	X	
Is blow-by present?	X	X	MAJOR or MINOR
Do you see oil in the coolant?	X	X	
Pressure check the cooling system	X	X	PASS or FAIL
Is the clutch in good operating condition?	X	X	Rate (1-10): <u>Autome 8.5</u>

Brake Lining: Front R: 50% 70% Tag Axle R: _____ L: _____ 1st Axle R: 70% 70% 2nd Axle R: NA L: NA

Tire Tread Percentage: Front 15-20% Tag Axle: _____ 1st Axle: 30% 2nd Axle: NA

Comments:

Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10

Comments:

NEED ETHER TO START!

Other Comments:

CAN'T SEE COOLANT.

Inspector Print:

BRANT

Date:

8-29-23

Inspector Signature:

Jack Brant

*** This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way ***