

# Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

Auction Date: 10/13

Stock Number: 70124

Lot Number: 736,398

## HESS REPORT SHEET

\*\*\* ALL Trucks are For Sale AS IS, WHERE IS \*\*\*

\*\*\* This is NOT A WARRANTY! \*\*\*

Truck Type (Circle one): Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: \_\_\_\_\_

Year: 2020 Make: Freightliner Model: ASCADIA Vin #: MC8330

Engine: Make: DET Model: DD13 HP: 525

Odometer Reading: 736,400 ECM Reading: \_\_\_\_\_

| Task                                                                                                                                                | Yes                                 | No                                  | Comments                                           |
|-----------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|-------------------------------------|----------------------------------------------------|
| Does the Truck Start?                                                                                                                               | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | Jump Start: <u>YES</u> or <u>NO</u>                |
| Does the motor idle and run normally?                                                                                                               | <input checked="" type="checkbox"/> | <input type="checkbox"/>            |                                                    |
| Does the truck have the Emission Deleted?                                                                                                           | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |                                                    |
| Does the Transmission operate in all gears?                                                                                                         | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |                                                    |
| Does the Air load in normal time?                                                                                                                   | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |                                                    |
| Are there any fluid leaks?                                                                                                                          | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <u>OIL</u> or <u>COOLANT</u> MAJOR or <u>MINOR</u> |
| Do you see coolant in the oil?                                                                                                                      | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |                                                    |
| Is the oil pressure at idle within OEM specs?                                                                                                       | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |                                                    |
| Is blow-by present?                                                                                                                                 | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | MAJOR or MINOR                                     |
| Do you see oil in the coolant?                                                                                                                      | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |                                                    |
| Pressure check the cooling system                                                                                                                   | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <u>PASS</u> or <u>FAIL</u>                         |
| Is the clutch in good operating condition?                                                                                                          | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Rate (1-10): <u>Automatic</u>                      |
| Brake Lining: Front R: <u>DISC</u> <u>CANT-SEE</u> Tag Axle R: _____ L: _____ 1st Axle R: <u>CANT-SEE</u> L: <u>DISC</u> 2nd Axle R: _____ L: _____ |                                     |                                     |                                                    |

Tire Tread Percentage: Front LF 50% Tag Axle: \_\_\_\_\_ 1st Axle: LF 70% 2nd Axle: RF 70%

Comments: RF 30% LF 80% RF 30%

Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10 8

Comments: LITTLE HARD DAMAGE

Other Comments: \_\_\_\_\_

Inspector Print: BRANT

Date: 8-29-23

Inspector Signature: Jak Brant

\*\*\* This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way \*\*\*