

Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

Blue

Auction Date: Oct
 Stock Number: ~~81249~~
 Lot Number: 70208

HESS REPORT SHEET

*** ALL Trucks are For Sale AS IS, WHERE IS ***
 *** This is NOT A WARRANTY! ***

433,103

Truck Type (Circle one): Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: _____
 Year: 2015 Make: Peterbilt Model: 384 Vin #: 269939
 Engine: Make: PACCAR Model: MX13 HP: 340/455
 Odometer Reading: 433105 ECM Reading: _____

Task	Yes	No	Comments
Does the Truck Start?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Jump Start <u>YES</u> or <u>NO</u>
Does the motor idle and run normally?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Does the truck have the Emission Deleted?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Does the Transmission operate in all gears?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Does the Air load in normal time?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Are there any fluid leaks?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OIL or COOLANT MAJOR or MINOR
Do you see coolant in the oil?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Is the oil pressure at idle within OEM specs?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Is blow-by present?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	MAJOR or MINOR
Do you see oil in the coolant?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Pressure check the cooling system	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<u>PASS</u> or FAIL
Is the clutch in good operating condition?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Rate (1-10): <u>Automatic</u>

Brake Lining: Front R: 80% Tag Axle R: 80% L: 80% 1st Axle R: 60% L: 60% 2nd Axle R: 80% L: 80%

Tire Tread Percentage: Front: 80% Tag Axle: 80% 1st Axle: 40% L: 60% 2nd Axle: 30% R: 30%

Comments: _____
 Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10 7

Comments: _____

Other Comments: _____

Inspector Print: BRAUT Date: 8-28-23

Inspector Signature: Joek Braut

*** This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way ***