

Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

white

Auction Date: OCT

Stock Number: 70252

Lot Number: _____

HESS REPORT SHEET

*** ALL Trucks are For Sale AS IS, WHERE IS ***

*** This is NOT A WARRANTY! ***

Truck Type (Circle one): Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: _____

Year: 2016 Make: Freightliner Model: Columbia Vin #: GX7323

Engine: Make: DET Model: LOSELDES HP: ?

Odometer Reading: DON'T WORK ECM Reading: _____

Task	Yes	No	Comments
Does the Truck Start?	<u>X</u>		Jump Start: YES or <u>NO</u>
Does the motor idle and run normally?		<u>X</u>	
Does the truck have the Emission Deleted?		<u>X</u>	<u>IS NONE</u>
Does the Transmission operate in all gears?	<u>X</u>		
Does the Air load in normal time?	<u>X</u>		
Are there any fluid leaks?	<u>X</u>		OIL or COOLANT MAJOR or <u>MINOR</u>
Do you see coolant in the oil?		<u>X</u>	
Is the oil pressure at idle within OEM specs?	<u>X</u>		
Is blow-by present?	<u>X</u>		MAJOR or MINOR
Do you see oil in the coolant?	<u>X</u>	<u>X</u>	
Pressure check the cooling system	<u>X</u>		PASS or FAIL
Is the clutch in good operating condition?	<u>X</u>		Rate (1-10): <u>4</u>

Brake Lining: Front R: 90% L: 90% Tag Axle R: _____ L: _____ 1st Axle R: 40% L: 40% 2nd Axle R: 60% L: 60%

Tire Tread Percentage: Front: 20% Tag Axle: _____ 1st Axle: 80% 2nd Axle: 80%

Comments: CK Eng Lite ON & RED STOP Eng Lite ON.

Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10

Comments: HOOD Damage. ABS Lite ON.

Other Comments: (GLIDER KIT) PARK BRAKE, Lite ON.

Inspector Print: BRANT

Date: 9-11-23

Inspector Signature: Jack Brant

*** This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way ***

DRIVER
windshield
Two
STONE
CHIPS.

ODOMETER DON'T WORK!