

# Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

Black

Auction Date: Oct

Stock Number: 70595

Lot Number: \_\_\_\_\_

## HESS REPORT SHEET

\*\*\* ALL Trucks are For Sale AS IS, WHERE IS \*\*\*

\*\*\* This is NOT A WARRANTY! \*\*\*

964,636

Truck Type (Circle one): Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: \_\_\_\_\_

Year: 2012 Make: International Model: ProStar Vin #: 663434

Engine: Make: INT Model: MAYFORSE HP: 450

Odometer Reading: 964,638 ECM Reading: 12.4L

Task	Yes	No	Comments
Does the Truck Start?	X		Jump Start: YES or <u>NO</u>
Does the motor idle and run normally?	X		
Does the truck have the Emission Deleted?		X	
Does the Transmission operate in all gears?	X		
Does the Air load in normal time?	X		
Are there any fluid leaks?	X		OIL or COOLANT MAJOR or <u>MINOR</u>
Do you see coolant in the oil?		X	
Is the oil pressure at idle within OEM specs?	X		
Is blow-by present?	X		MAJOR or MINOR
Do you see oil in the coolant?		X	
Pressure check the cooling system	X		PASS or FAIL
Is the clutch in good operating condition?	X		Rate (1-10): <u>2</u>

Brake Lining: Front R: 60% L: 60% Tag Axle R: \_\_\_\_\_ L: \_\_\_\_\_ 1st Axle R: 10% L: 20% 2nd Axle R: 10% L: 10%

Tire Tread Percentage: Front LF-20% Tag Axle: \_\_\_\_\_ 1st Axle: 0% 2nd Axle: LRF-10% RRE  
RF-0% LRO-0% RRO > 300%

Comments:

Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10

Comments:

PASS-SIDE Damage OF TR.

Other Comments:

CLUTCH PEDAL, Push HARD. NEED CLUTCH ADJ.

Inspector Print: BRANT

Date: 7-11-23

Inspector Signature: Jack Brant

\*\*\* This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way \*\*\*