

# Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

Brown

Auction Date: 10/13  
Stock Number: 68651  
Lot Number: \_\_\_\_\_

## HESS REPORT SHEET

\*\*\* ALL Trucks are For Sale AS IS, WHERE IS \*\*\*

\*\*\* This is NOT A WARRANTY! \*\*\*

767,697.8

Truck Type (Circle one): Sleeper / <u>Daycab</u> / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: _____			
Year: <u>2014</u> Make: <u>VOLVO</u> Model: <u>VNL</u> Vin #: <u>156015</u>			
Engine: Make: <u>VOLVO</u> Model: <u>D13</u> HP: <u>405</u>			
Odometer Reading: <u>767,697</u> ECM Reading: _____			
Task	Yes	No	Comments
Does the Truck Start?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Jump Start: YES or NO
Does the motor idle and run normally?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Does the truck have the Emission Deleted?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Does the Transmission operate in all gears?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Does the Air load in normal time?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Are there any fluid leaks?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OIL or COOLANT MAJOR or MINOR
Do you see coolant in the oil?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Is the oil pressure at idle within OEM specs?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Is blow-by present?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	MAJOR or MINOR
Do you see oil in the coolant?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Pressure check the cooling system	<input checked="" type="checkbox"/>	<input type="checkbox"/>	PASS or FAIL
Is the clutch in good operating condition?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Rate (1-10): <u>4</u>
Brake Lining: Front R: <u>70%</u> L: <u>70%</u> Tag Axle R: _____ L: _____ 1 <sup>st</sup> Axle R: _____ L: _____ 2 <sup>nd</sup> Axle R: <u>NA</u> L: <u>NA</u>			
Tire Tread Percentage: Front: <u>100%</u> Tag Axle: _____ 1 <sup>st</sup> Axle: _____ 2 <sup>nd</sup> Axle: <u>NA</u>			
Comments: _____			
Cosmetic Condition: Rate 1 2 3 <u>4</u> 5 6 7 8 9 10			
Comments: <u>CK Eng Lite ON.</u>			
Other Comments: _____			

Inspector Print: BRANT

Date: 6-28-23

Inspector Signature: Jack Brant

\*\*\* This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way \*\*\*

1:00:01

15