

Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

White

Auction Date: 10/13

Stock Number: 70052

Lot Number:

HESS REPORT SHEET

*** ALL Trucks are For Sale AS IS, WHERE IS ***

*** This is NOT A WARRANTY! ***

517761

Truck Type (Circle one): Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: _____

Year: 2020 Make: Freightliner Model: AS Cedia Vin #: MC8294

Engine: Make: DET Model: 0013 HP: 525

Odometer Reading: 517,762 ECM Reading: _____

Task	Yes	No	Comments
Does the Truck Start?	☒	☐	Jump Start: YES or <u>NO</u>
Does the motor idle and run normally?	☒	☐	
Does the truck have the Emission Deleted?	☐	☒	
Does the Transmission operate in all gears?	☒	☐	
Does the Air load in normal time?	☒	☐	
Are there any fluid leaks?	☒	☐	OIL or COOLANT MAJOR or <u>MINOR</u>
Do you see coolant in the oil?	☒	☐	
Is the oil pressure at idle within OEM specs?	☒	☐	
Is blow-by present?	☒	☐	MAJOR or MINOR
Do you see oil in the coolant?	☒	☐	
Pressure check the cooling system	☒	☐	<u>PASS</u> or FAIL
Is the clutch in good operating condition?	☒	☐	Rate (1-10): <u>Automatic</u>
Brake Lining: Front R: <u>CAN'T - SEE</u> Tag Axle R: _____ L: _____ 1st Axle R: _____ L: _____ 2nd Axle R: _____ L: _____			
Tire Tread Percentage: Front: <u>50%</u> Tag Axle: _____ 1st Axle: <u>LFT > 80%</u> 2nd Axle: <u>LFT > 100%</u> <u>RFT > 30%</u>			
Comments:			
Cosmetic Condition: Rate 1 2 3 4 5 6 <u>10</u> 8 9 10			
Comments:			
Other Comments:			

Inspector Print: BRANT

Date: 8-22-23

Inspector Signature: Jack Brant

*** This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way ***