

Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

White
Auction Date: 10/13
Stock Number: 70368
Lot Number: _____

HESS REPORT SHEET

*** ALL Trucks are For Sale AS IS, WHERE IS ***

*** This is NOT A WARRANTY! ***

37,245.6

Truck Type (Circle one): Sleeper / Daycab / <u>Jockey</u> / Dump / Box / Flatbed / Reefer / Chassis / Other: _____			
Year: <u>2010</u> Make: <u>CAPACITY</u> Model: <u>T56500</u> Vin #: <u>021212</u>			
Engine: Make: <u>Cummins</u> Model: <u>6-72</u> HP: <u>200</u>			
Odometer Reading: <u>37,246</u>		ECM Reading: _____	
Task	Yes	No	Comments
Does the Truck Start?	☒	☐	Jump Start: YES or <u>NO</u>
Does the motor idle and run normally?	☒	☐	
Does the truck have the Emission Deleted?	☒	☒	
Does the Transmission operate in all gears?	☒	☐	
Does the Air load in normal time?	☒	☐	
Are there any fluid leaks?	☒	☐	OIL or COOLANT MAJOR or <u>MINOR</u>
Do you see coolant in the oil?	☒	☒	
Is the oil pressure at idle within OEM specs?	☒	☐	
Is blow-by present?	☒	☒	MAJOR or MINOR
Do you see oil in the coolant?	☒	☒	
Pressure check the cooling system	☒	☐	<u>PASS</u> or FAIL
Is the clutch in good operating condition?	☒	☐	Rate (1-10): <u>Automatic</u>
CAN'T SEE CAN'T SEE			
Brake Lining: Front R: _____ L: _____ Tag Axle R: _____ L: _____ 1st Axle R: <u>70%</u> L: <u>70%</u> 2nd Axle R: <u>70%</u> L: <u>70%</u>			
Tire Tread Percentage: Front: <u>30%</u> Tag Axle: _____ 1st Axle: <u>90%</u> 2nd Axle: <u>90%</u>			
Comments: _____			
Cosmetic Condition: Rate 1 2 3 4 <u>5</u> 6 7 8 9 10			
Comments: <u>RADIATOR TOP SPOUT, IS CRACK.</u>			
Other Comments: <u>CK Eng Lite ON.</u>			

Inspector Print: BRANT

Date: 9-05-23

Inspector Signature: Jack Brant

*** This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way ***