

Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

Auction Date: Oct
Stock Number: 70253
Lot Number: _____

HESS REPORT SHEET

*** ALL Trucks are For Sale AS IS, WHERE IS ***

*** This is NOT A WARRANTY! ***

382,810.8

Truck Type (Circle one): Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: _____

Year: 2016 Make: Freightliner Model: Columbia Vin #: HH3770

Engine: Make: DET Model: 60 SERIES HP: ?

Odometer Reading: 382,812 ECM Reading: _____

Task	Yes	No	Comments
Does the Truck Start?	<u>X</u>		Jump Start: <u>YES</u> or <u>NO</u>
Does the motor idle and run normally?	<u>X</u>		
Does the truck have the Emission Deleted?		<u>X</u>	<u>IS None</u>
Does the Transmission operate in all gears?	<u>X</u>		
Does the Air load in normal time?	<u>X</u>		
Are there any fluid leaks?	<u>X</u>		OIL or COOLANT MAJOR or <u>MINOR</u>
Do you see coolant in the oil?	<u>X</u>	<u>X</u>	
Is the oil pressure at idle within OEM specs?	<u>X</u>	<u>X</u>	
Is blow-by present?	<u>X</u>		MAJOR or <u>MINOR</u>
Do you see oil in the coolant?	<u>X</u>	<u>X</u>	
Pressure check the cooling system	<u>X</u>		<u>PASS</u> or FAIL
Is the clutch in good operating condition?	<u>X</u>		Rate (1-10): <u>4</u>

Brake Lining: Front R: 60% L: 60% Tag Axle R: _____ L: _____ 1st Axle R: 30% L: 30% 2nd Axle R: 30% L: 30%

Tire Tread Percentage: Front: 60% Tag Axle: _____ 1st Axle: 80% 2nd Axle: 70%

Comments: FENDER BEHINE, RF STEER TIRE, IS Damage
Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10

Comments: (GLIDER KIT.) Think

Other Comments: PASS-SIDE, WEST COAST MIRROR COVER Missing.

Inspector Print: BRANT

Date: 9-12-23

Inspector Signature: Jack Brant

*** This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way ***