

Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

white

Auction Date: OCT

Stock Number: 70734

Lot Number: _____

HESS REPORT SHEET

*** ALL Trucks are For Sale AS IS, WHERE IS ***

*** This is NOT A WARRANTY! ***

688,756.4

Truck Type (Circle one): Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: _____

Year: 2015 Make: Volvo Model: _____ Vin #: 177190

Engine: Make: VOLVO Model: D13 HP: 405

Odometer Reading: 688757 ECM Reading: _____

Task	Yes	No	Comments
Does the Truck Start?	☒	☐	Jump Start: YES or NO
Does the motor idle and run normally?	☒	☐	
Does the truck have the Emission Deleted?	☐	☒	
Does the Transmission operate in all gears?	☐	☒	
Does the Air load in normal time?	☒	☐	
Are there any fluid leaks?	☒	☐	OIL or COOLANT
Do you see coolant in the oil?	☒	☐	MAJOR or MINOR
Is the oil pressure at idle within OEM specs?	☒	☐	
Is blow-by present?	☒	☐	MAJOR or MINOR
Do you see oil in the coolant?	☒	☐	
Pressure check the cooling system	☒	☐	PASS or FAIL
Is the clutch in good operating condition?	☒	☐	Rate (1-10): <u>Automatic</u>
Brake Lining: Front R: <u>CAN'T SEE</u> Tag Axle R: _____ L: _____ 1st Axle R: <u>40%</u> L: <u>40%</u> 2nd Axle R: <u>40%</u> L: <u>40%</u>			
Tire Tread Percentage: Front: <u>80%</u> Tag Axle: _____ 1st Axle: <u>40%</u> 2nd Axle: <u>40%</u>			
Comments: <u>LEFT LFO/40% RFI-10% RFO-40%</u>			
Cosmetic Condition: Rate 1 2 3 4 5 <u>6</u> 7 8 9 10			
Comments: <u>CK Eng Lite ON.</u>			
Other Comments: <u>when putting TRAN, INTO DRIVE OR REV, IT</u>			

Inspector Print: BRANT

Date: 9-12-23

JERK'S

Inspector Signature: Jack Brant

*** This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way ***