

Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

white

Auction Date: Oct

Stock Number: 71004

Lot Number: _____

HESS REPORT SHEET

*** ALL Trucks are For Sale AS IS, WHERE IS ***

*** This is NOT A WARRANTY! ***

743-296

Truck Type (Circle one) Sleeper Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: _____

Year 2015 Make: Freightliner Model: Cascadia Vin #: GL4700

Engine: Make: DET Model: ? HP: ?

Odometer Reading: 743,297 ECM Reading: _____

Task	Yes	No	Comments
Does the Truck Start?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Jump Start: YES or NO <u>NO</u>
Does the motor idle and run normally?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Does the truck have the Emission Deleted?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Does the Transmission operate in all gears?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Does the Air load in normal time?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Are there any fluid leaks?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OIL or COOLANT MAJOR or MINOR
Do you see coolant in the oil?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Is the oil pressure at idle within OEM specs?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Is blow-by present?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	MAJOR or MINOR
Do you see oil in the coolant?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Pressure check the cooling system	<input checked="" type="checkbox"/>	<input type="checkbox"/>	PASS or FAIL <u>PASS</u>
Is the clutch in good operating condition?	<input type="checkbox"/>	<input type="checkbox"/>	Rate (1-10): _____ <u>Automatic</u>

Brake Lining: Front R: 80% L: 80% Tag Axle R: _____ L: _____ 1st Axle R: 80% L: 80% 2nd Axle R: 80% L: 80%

Tire Tread Percentage: Front: LF-31% Tag Axle: _____ 1st Axle: 20% 2nd Axle: RR-20% SUPER Single

Comments: RF-10% LR-100%

Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10

Comments:

Other Comments: _____

Inspector Print: BRANT

Date: 9-18-23

Inspector Signature: Jack Brant

*** This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way ***