

Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

Green

Auction Date: 10/13

Stock Number: 70866

Lot Number: _____

HESS REPORT SHEET

*** ALL Trucks are For Sale AS IS, WHERE IS ***

*** This is NOT A WARRANTY! ***

485,386.4

Truck Type (Circle one): Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: _____

Year: 2013 Make: Volvo Model: VNL 300 Vin #: 145002

Engine: Make: Volvo Model: D13 HP: 425

Odometer Reading: 485,387 ECM Reading: _____

Task	Yes	No	Comments
Does the Truck Start?	☒	☐	Jump Start: YES or <u>NO</u>
Does the motor idle and run normally?	☒	☐	
Does the truck have the Emission Deleted?	☒	☒	
Does the Transmission operate in all gears?	☒	☒	
Does the Air load in normal time?	☒	☒	
Are there any fluid leaks?	☒	☒	OIL or COOLANT MAJOR or <u>MINOR</u>
Do you see coolant in the oil?	☒	☒	
Is the oil pressure at idle within OEM specs?	☒	☒	
Is blow-by present?	☒	☒	MAJOR or MINOR
Do you see oil in the coolant?	☒	☒	
Pressure check the cooling system	☒	☒	PASS or FAIL
Is the clutch in good operating condition?	☒	☒	Rate (1-10): <u>4</u>

Brake Lining: Front R: CAN'T-SEE Tag Axle R: _____ L: _____ 1st Axle R: 20% L: 20% 2nd Axle R: CAN'T-SEE

Tire Tread Percentage: Front 80% Tag Axle: _____ 1st Axle: 70% 2nd Axle: LRI-40% RRI
LRO-70% RRO > 70%

Comments: CK Eng Lite ON.

Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10

Comments: Little Hood Damage. TAIL-PIPE IN CAB

Other Comments: BACK OF CAB, RUSTED.

Inspector Print: BRANT

Date: 9-18-23

Inspector Signature: Jack Brant

*** This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way ***