

Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

WHITE
Auction Date: 10/13
Stock Number: 70369
Lot Number: _____

HESS REPORT SHEET

*** ALL Trucks are For Sale AS IS, WHERE IS ***

*** This is NOT A WARRANTY! ***

HZ8851

Truck Type (Circle one): Sleeper / Daycab / Dump / Box / Flatbed / Reefer / Chassis / Other: _____

Year: 2017 Make: FREIGHTLINER Model: CASCADE Vin #: HZ8851

Engine: Make: DET Model: DD13 HP: 525

Odometer Reading: 660,624 ECM Reading: _____

Task	Yes	No	Comments
Does the Truck Start?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Jump Start: YES or <u>NO</u>
Does the motor idle and run normally?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Does the truck have the Emission Deleted?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Does the Transmission operate in all gears?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Does the Air load in normal time?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Are there any fluid leaks?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OIL or COOLANT MAJOR or <u>MINOR</u>
Do you see coolant in the oil?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Is the oil pressure at idle within OEM specs?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Is blow-by present?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	MAJOR or MINOR
Do you see oil in the coolant?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Pressure check the cooling system	<input checked="" type="checkbox"/>	<input type="checkbox"/>	PASS or FAIL
Is the clutch in good operating condition?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Rate (1-10): <u>4</u>

Brake Lining: Front R: DISC L: CAN'T SEE Tag Axle R: _____ L: _____ 1st Axle R: CAN'T SEE L: DISC 2nd Axle R: _____ L: _____

Tire Tread Percentage: Front: 70% Tag Axle: _____ 1st Axle: 90% 2nd Axle: 40%

Comments: RF, 40%

Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10

Comments: DRIVER AIR FOLLY Behind CAB, BROKE OFF.

Other Comments: _____

Inspector Print: BRANT

Date: 9-18-23

Inspector Signature: Joel Brant

*** This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way ***