

# Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

Gold

Auction Date: OCT

Stock Number: 70905

Lot Number: \_\_\_\_\_

## HESS REPORT SHEET

\*\*\* ALL Trucks are For Sale AS IS, WHERE IS \*\*\*

\*\*\* This is NOT A WARRANTY! \*\*\*

Truck Type (Circle one): Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other Car Carrier

Year: 2012 Make: Peterbilt Model: 389 Vin #: 135008

Engine: Make: Cummins Model: ISX15 HP: 485

Odometer Reading: 778,200 ECM Reading: \_\_\_\_\_

| Task                                          | Yes                                 | No                                  | Comments                      |
|-----------------------------------------------|-------------------------------------|-------------------------------------|-------------------------------|
| Does the Truck Start?                         | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | Jump Start: YES or <u>NO</u>  |
| Does the motor idle and run normally?         | <input checked="" type="checkbox"/> | <input type="checkbox"/>            |                               |
| Does the truck have the Emission Deleted?     | <input type="checkbox"/>            | <input checked="" type="checkbox"/> |                               |
| Does the Transmission operate in all gears?   | <input type="checkbox"/>            | <input type="checkbox"/>            |                               |
| Does the Air load in normal time?             | <input checked="" type="checkbox"/> | <input type="checkbox"/>            |                               |
| Are there any fluid leaks?                    | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | OIL or COOLANT MAJOR or MINOR |
| Do you see coolant in the oil?                | <input type="checkbox"/>            | <input checked="" type="checkbox"/> |                               |
| Is the oil pressure at idle within OEM specs? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            |                               |
| Is blow-by present?                           | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | MAJOR or <u>MINOR</u>         |
| Do you see oil in the coolant?                | <input type="checkbox"/>            | <input checked="" type="checkbox"/> |                               |
| Pressure check the cooling system             | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <u>PASS</u> or FAIL           |
| Is the clutch in good operating condition?    | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | Rate (1-10): _____            |

Brake Lining: Front R: 20% L: 20% Tag Axle R: \_\_\_\_\_ L: \_\_\_\_\_ 1st Axle R: 80% L: 80% 2nd Axle R: 80% L: 80%

Tire Tread Percentage: Front LF 10% Tag Axle: \_\_\_\_\_ 1st Axle: LF 40% 2nd Axle: 40%

Comments: RF 20% LF 40% RF 10%

Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10

Comments: \_\_\_\_\_

Other Comments: \_\_\_\_\_

Inspector Print: BRANT

Date: 7-19-23

Inspector Signature: Jack Brant

\*\*\* This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way \*\*\*

NOTE, DID NOT DRIVE complete unit!