

# Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

WHITE

Auction Date: 10/31  
Stock Number: 70544  
Lot Number: \_\_\_\_\_

## HESS REPORT SHEET

\*\*\* ALL Trucks are For Sale AS IS, WHERE IS \*\*\*

\*\*\* This is NOT A WARRANTY! \*\*\*

391,564

Truck Type (Circle one): Sleeper (Daycab) / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: \_\_\_\_\_

Year: 2014 Make: INTERNATIONAL Model: PROSTAR Vin #: 015938

Engine: Make: NAVISTAR Model: N13 HP: 450

Odometer Reading: 391,566 ECM Reading: \_\_\_\_\_

Task	Yes	No	Comments
Does the Truck Start?	<u>X</u>		Jump Start: YES or NO <u>(NO)</u>
Does the motor idle and run normally?		<u>X</u>	
Does the truck have the Emission Deleted?		<u>X</u>	
Does the Transmission operate in all gears?	<u>X</u>		
Does the Air load in normal time?		<u>X</u>	<u>VERY, VERY, SLOW</u>
Are there any fluid leaks?	<u>X</u>		OIL or COOLANT MAJOR or MINOR <u>(MINOR)</u>
Do you see coolant in the oil?		<u>X</u>	
Is the oil pressure at idle within OEM specs?	<u>X</u>		
Is blow-by present?	<u>X</u>		MAJOR or MINOR <u>(MINOR)</u>
Do you see oil in the coolant?		<u>X</u>	
Pressure check the cooling system	<u>X</u>		PASS or FAIL <u>(PASS)</u>
Is the clutch in good operating condition?	<u>X</u>		Rate (1-10): <u>4</u>

Brake Lining: Front R: 20% L: 60% Tag Axle R: \_\_\_\_\_ L: \_\_\_\_\_ 1st Axle R: 60% L: 60% 2nd Axle R: 40% L: 40%

Tire Tread Percentage: Front RF-20% Tag Axle: \_\_\_\_\_ 1st Axle: 40% 2nd Axle: 80%

Comments: RF-20% 40% (ck Eng Lite ON)

Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10 4

Comments: DRIVER SEAT, TORN, SCREEN IN RF STEERING

Other Comments: NO OIL ON DIPSTICK

Inspector Print: BRANT

Date: 9-25-23

Inspector Signature: Jack Brant

\*\*\* This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way \*\*\*

AIR PRESSURE TAKE' FOR EVER!