Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

Auction Date: 10/13
Stock Number: 21270
Lot Number:

HESS REPORT SHEET

*** ALL Trucks are For Sale AS IS, WHERE IS ***

*** This is NOT A WARRANTY! ***

	11113 13 140	JI A VVAN	AVACET I	<u> </u>	
Truck Type (Circle one): Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer/ Chassis / Other:					
Year: <u>2018</u> Make: <u>KW</u>	Model	768	<i>⊙</i> Vin #:_		204816
Engine: Make: <u>\(\frac{\partial}{\phi} \tau_\text{\text{\$\theta}} \text{\$\text{\$\text{\$\theta}}} \)</u>	rariay	Model:	X15	нр: <u>\$00</u>	
Odometer Reading: 389,367 ECM Reading:					
Task J	Yes	No		Comments	•
Does the Truck Start?	X		Jump Start: YES	er No.	
Does the motor idle and run normally?	/X				
Does the truck have the Emission Deleted?	(X			
Does the Transmission operate in all gears?		· •			
Does the Air load in normal time?	×	/32	N		
Are there any fluid leaks?	X		OIL OF EOOLANT		MAJOR or MINOR
Do you see coolant in the oil?	/			•	
Is the oil pressure at idle within OEM specs?	X				
Is blow-by present?	0/XX		MAJOR or MINO	or)	
Do you see oil in the coolant?	1				
Pressure check the cooling system		()	PASS or FAIL		
Is the clutch in good operating condition?)	Rate (1-10):	Aut	onexic
Brake Lining: Front R: 2 Tag Axie R: L: 1st Axie R: CA: W Tad Axie R: L: LICC)					
Tire Tread Percentage: Front: Zoha Tag Axle:1st Axle: Zoha Axle: Zoha					
Comments:					
Cosmetic Condition: Rate 1 2 3 4 5 6 🗗 8 9 10					
Other Comments		•			
Other Comments:					
D.					

Inspector Print:

Date: 7-27-23

Inspector Signature:

*** This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way ***