

Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

Auction Date: 10/13

Stock Number: 71368

Lot Number: _____

HESS REPORT SHEET

*** ALL Trucks are For Sale AS IS, WHERE IS ***

*** This is NOT A WARRANTY! ***

902,540.0

Truck Type (Circle one) Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: _____

Year: 2014 Make: Kenworth Model: T680 Vin #: 400899

Engine: Make: PACCAR Model: MX-13 HP: 340/455

Odometer Reading: 902,541 ECM Reading: _____

Task	Yes	No	Comments
Does the Truck Start?	☒	☐	Jump Start: YES or NO <u>NO</u>
Does the motor idle and run normally?	☒	☐	
Does the truck have the Emission Deleted?	☐	☒	
Does the Transmission operate in all gears?	☐	☒	
Does the Air load in normal time?	☒	☐	
Are there any fluid leaks?	☒	☐	OIL or COOLANT MAJOR or MINOR <u>MINOR</u>
Do you see coolant in the oil?	☒	☐	
Is the oil pressure at idle within OEM specs?	☒	☐	
Is blow-by present?	☒	☐	MAJOR or MINOR
Do you see oil in the coolant?	☒	☐	
Pressure check the cooling system	☒	☐	PASS or FAIL <u>PASS</u>
Is the clutch in good operating condition?	☒	☐	Rate (1-10): <u>Automatic</u>

Brake Lining: Front R: 50% L: 50% Tag Axle R: _____ L: _____ 1st Axle R: 40% L: 40% 2nd Axle R: 70% L: 70%

Tire Tread Percentage: Front: 80% Tag Axle: _____ 1st Axle: 30% 2nd Axle: LRI LRO/30% RRI-70% RRO-0%

Comments:

Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10

Comments:

HOOD & BUMPER Damage

Other Comments:

DAMAGE ON DRIVER SIDE, Bunk.

Inspector Print: BRANT

Date: 9-27-23

Inspector Signature: Jack Brant

*** This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way ***