

Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

WHITE

Auction Date: 10/13

Stock Number: 71388

Lot Number: 680,470.5

HESS REPORT SHEET

*** ALL Trucks are For Sale AS IS, WHERE IS ***

*** This is NOT A WARRANTY! ***

Truck Type (Circle one): Sleeper / <u>Daycab</u> / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: _____			
Year: <u>2012</u> Make: <u>VOLVO</u> Model: <u>VNL</u> Vin #: <u>549666</u>			
Engine: Make: <u>VOLVO</u> Model: <u>D13</u> HP: <u>425</u>			
Odometer Reading: <u>680,471</u> ECM Reading: _____			
Task	Yes	No	Comments
Does the Truck Start?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Jump Start: YES or NO <u>NO</u>
Does the motor idle and run normally?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Does the truck have the Emission Deleted?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Does the Transmission operate in all gears?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Does the Air load in normal time?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Are there any fluid leaks?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OIL or COOLANT MAJOR or MINOR <u>MAJOR</u>
Do you see coolant in the oil?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Is the oil pressure at idle within OEM specs?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Is blow-by present?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	MAJOR or MINOR
Do you see oil in the coolant?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Pressure check the cooling system	<input checked="" type="checkbox"/>	<input type="checkbox"/>	PASS or FAIL
Is the clutch in good operating condition?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Rate (1-10): <u>Automotive</u>
Brake Lining: Front R: <u>60%</u> L: <u>40%</u> Tag Axle R: _____ L: _____ 1st Axle R: <u>30%</u> L: <u>30%</u> 2nd Axle R: <u>NA</u> L: <u>NA</u>			
Tire Tread Percentage: Front: <u>100%</u> Tag Axle: _____ 1st Axle: <u>100%</u> 2nd Axle: <u>NA</u>			
Comments: _____			
Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10 <u>5</u>			
Comments: <u>Hood Damage</u>			
Other Comments: <u>CK Eng Lite ON</u>			

Inspector Print: BRANT

Date: 9-27-23

Inspector Signature: Jack Brant

*** This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way ***