

Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

Auction Date: 10/13

Stock Number: 71416

Lot Number: _____

HESS REPORT SHEET

*** ALL Trucks are For Sale AS IS, WHERE IS ***

*** This is NOT A WARRANTY! ***

1,255,623.7

Truck Type (Circle one): Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: _____

Year: 2012 Make: VOLVO Model: VNL Vin #: 546405

Engine: Make: VOLVO Model: D13 HP: 425

Odometer Reading: 1,255,625 ECM Reading: _____

Task	Yes	No	Comments
Does the Truck Start?	☒	☐	Jump Start: YES or NO
Does the motor idle and run normally?	☒	☐	
Does the truck have the Emission Deleted?	☒	☒	
Does the Transmission operate in all gears?	☒	☐	
Does the Air load in normal time?	☒	☐	
Are there any fluid leaks?	☒	☐	OIL or COOLANT MAJOR or MINOR
Do you see coolant in the oil?	☒	☐	
Is the oil pressure at idle within OEM specs?	☒	☐	
Is blow-by present?	☒	☐	MAJOR or MINOR
Do you see oil in the coolant?	☒	☐	
Pressure check the cooling system	☒	☐	PASS or FAIL
Is the clutch in good operating condition?	☒	☐	Rate (1-10): <u>Automatic</u>

Brake Lining: Front R: CAN'T-SEE L: 50% Tag Axle R: 50% L: 50% 1st Axle R: 20% L: 50% 2nd Axle R: 20% L: 20%
Tire Tread Percentage: Front R: 80% Tag Axle: 80% 1st Axle R: 20% L: 90% 2nd Axle: 20% R: 30% L: 30%

Comments: DRIVER FUEL TANK AIR FOIL, Damage.
Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10

Comments: HOOD & BUMPER Damage. ABS Light ON

Other Comments: DRIVER SIDE, Bunk Damage cK Eng Lite ON.

Inspector Print: BRANT

Date: 9-28-23

Inspector Signature: Jack Brant

*** This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way ***

Windshield CRACK!

RFI > 90%
RFO