

# Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

Blue

Auction Date: Oct

Stock Number: 70688

Lot Number: 851,649

## HESS REPORT SHEET

\*\*\* ALL Trucks are For Sale AS IS, WHERE IS \*\*\*

\*\*\* This is NOT A WARRANTY! \*\*\*

Truck Type (Circle one): Sleeper Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: \_\_\_\_\_

Year: 2011 Make: Peterbilt Model: 386 Vin #: 126917

Engine: Make: Cummins Model: ISX15 HP: 485

Odometer Reading: 851,651 ECM Reading: \_\_\_\_\_

Task	Yes	No	Comments
Does the Truck Start?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Jump Start: YES or NO <u>NO</u>
Does the motor idle and run normally?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Does the truck have the Emission Deleted?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Does the Transmission operate in all gears?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Does the Air load in normal time?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Are there any fluid leaks?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OIL or COOLANT MAJOR or MINOR <u>MINOR</u>
Do you see coolant in the oil?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Is the oil pressure at idle within OEM specs?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Is blow-by present?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	MAJOR or MINOR <u>MINOR</u>
Do you see oil in the coolant?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Pressure check the cooling system	<input checked="" type="checkbox"/>	<input type="checkbox"/>	PASS or FAIL <u>FAIL</u>
Is the clutch in good operating condition?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Rate (1-10): <u>4</u>
(Disc) CAN'T SEE Brake Lining: Front R: _____ L: _____ Tag Axle R: _____ L: _____ 1st Axle R: <u>80%</u> L: <u>80%</u> 2nd Axle R: <u>80%</u> L: <u>80%</u>			
Tire Tread Percentage: Front: <u>40%</u> Tag Axle: _____ 1st Axle: <u>LF-20%</u> Axle: <u>20%</u> SUPER Single's Comments: <u>RF-40%</u>			
Cosmetic Condition: Rate 1 2 3 <u>4</u> 5 6 7 8 9 10			
Comments:			
Other Comments:			

Inspector Print: BRANT

Date: 9-28-23

Inspector Signature: Jack Brant

\*\*\* This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way \*\*\*