

Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

Red

Auction Date: 10/13

Stock Number: 71530

Lot Number: _____

HESS REPORT SHEET

*** ALL Trucks are For Sale AS IS, WHERE IS ***

*** This is NOT A WARRANTY! ***

460,283

Truck Type (Circle one): Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: _____

Year: 2016 Make: WESTERU STAR Model: S700XE Vin #: HK5443

Engine: Make: DET Model: ? HP: ?

Odometer Reading: 460,283 ECM Reading: _____

Task	Yes	No	Comments
Does the Truck Start?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Jump Start: YES or NO
Does the motor idle and run normally?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Does the truck have the Emission Deleted?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Does the Transmission operate in all gears?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Does the Air load in normal time?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Are there any fluid leaks?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OIL or COOLANT MAJOR or MINOR
Do you see coolant in the oil?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Is the oil pressure at idle within OEM specs?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Is blow-by present?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	MAJOR or MINOR
Do you see oil in the coolant?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Pressure check the cooling system	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	PASS or FAIL
Is the clutch in good operating condition?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Rate (1-10): _____
Brake Lining: Front R: <u>70%</u> L: <u>70%</u> Tag Axle R: _____ L: _____ 1st Axle R: _____ L: _____ 2nd Axle R: _____ L: _____			
Tire Tread Percentage: Front: <u>50%</u> Tag Axle: _____ 1st Axle: <u>50%</u> 2nd Axle: <u>20%</u>			
Comments: _____			
Cosmetic Condition: Rate 1 2 3 4 5 6 <u>7</u> 8 9 10			
Comments: _____			
Other Comments: _____			

Inspector Print: BRA NT

Date: 10-02-23

Inspector Signature: Jack Brant

*** This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way ***