

Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

SILVER

Auction Date: 10/13

Stock Number: 71744

Lot Number:

HESS REPORT SHEET

*** ALL Trucks are For Sale AS IS, WHERE IS ***

*** This is NOT A WARRANTY! ***

1251312

Truck Type (Circle one): Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other:

Year: 2007 Make: PETERBILT Model: 386 Vin #: 672312

Engine: Make: CAT Model: C15 HP: 3

Odometer Reading: 1731319 ECM Reading: ACERT

Task	Yes	No	Comments
Does the Truck Start?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Jump Start: YES or NO
Does the motor idle and run normally?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Does the truck have the Emission Deleted?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Does the Transmission operate in all gears?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Does the Air load in normal time?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Are there any fluid leaks?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OIL or COOLANT MAJOR or MINOR
Do you see coolant in the oil?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Is the oil pressure at idle within OEM specs?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Is blow-by present?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	MAJOR or MINOR
Do you see oil in the coolant?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Pressure check the cooling system	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	PASS or FAIL
Is the clutch in good operating condition?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Rate (1-10): <u>4</u>

Brake Lining: Front R: 0% L: 100% Tag Axle R: 30% L: 30% 1st Axle R: 30% L: 30% 2nd Axle R: 100% L: 30%

Tire Tread Percentage: Front RF-10% Tag Axle: 30% 1st Axle: 30% 2nd Axle: LR-50% LRO-50% RRC-30% RRO-20%

Comments:

Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10

Comments:

Bumper & GRILL Damage.

Other Comments:

Inspector Print: BRANT

Date: 10-02-23

Inspector Signature: Jack Brant

*** This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way ***