

Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

RED

Auction Date: 10/13

Stock Number: 70614

Lot Number:

HESS REPORT SHEET

*** ALL Trucks are For Sale AS IS, WHERE IS ***

*** This is NOT A WARRANTY! ***

Truck Type (Circle one): Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other:

Year: 2004 Make: FREIGHT LINCOR Model: CORONADO Vin #: N16931

Engine: Make: DET Model: 60 SERIES HP: 515

Odometer Reading: 314,037 ECM Reading:

| Task | Yes | No | Comments |
|---|-------------------------------------|-------------------------------------|-------------------------------|
| Does the Truck Start? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | Jump Start: YES or NO |
| Does the motor idle and run normally? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | |
| Does the truck have the Emission Deleted? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | IS NONE |
| Does the Transmission operate in all gears? | <input type="checkbox"/> | <input type="checkbox"/> | |
| Does the Air load in normal time? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | |
| Are there any fluid leaks? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | OIL or COOLANT MAJOR or MINOR |
| Do you see coolant in the oil? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | |
| Is the oil pressure at idle within OEM specs? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | |
| Is blow-by present? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | MAJOR or MINOR |
| Do you see oil in the coolant? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | |
| Pressure check the cooling system | <input checked="" type="checkbox"/> | <input type="checkbox"/> | PASS or FAIL |
| Is the clutch in good operating condition? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | Rate (1-10): |

Brake Lining: Front R: 50% 50% Tag Axle R: 20% L: 20% 1st Axle R: 20% L: 20% 2nd Axle R: 20% L: 20%

Tire Tread Percentage: Front: 80% Tag Axle: 100% 1st Axle: 100% 2nd Axle: 100%

Comments:

Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10

Comments:

GRILL Damage.

Other Comments:

ABS Lite ON

Inspector Print:

BRANT

Date:

10-03-23

Inspector Signature:

Jack Brant

*** This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way ***

CAME IN TOO LAST, TOO DRIVE!