

**Hess Auctioneers, LLC.**

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

BLUEAuction Date: 10/13Stock Number: 70664

Lot Number: \_\_\_\_\_

**HESS REPORT SHEET**

\*\*\* ALL Trucks are For Sale AS IS, WHERE IS \*\*\*

\*\*\* This is NOT A WARRANTY! \*\*\*

794,603.4Truck Type (Circle one) Sleeper Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: \_\_\_\_\_Year: 2016 Make: KENWORTH Model: T680 Vin #: 463219Engine: Make: Cummins Model: DX15 HP: 425Odometer Reading: 794,604 ECM Reading: \_\_\_\_\_

Task	Yes	No	Comments
Does the Truck Start?		<input checked="" type="checkbox"/>	Jump Start: <u>YES</u> or NO
Does the motor idle and run normally?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Does the truck have the Emission Deleted?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Does the Transmission operate in all gears?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Does the Air load in normal time?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Are there any fluid leaks?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<u>OIL</u> or COOLANT MAJOR or MINOR <u>MINOR</u>
Do you see coolant in the oil?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Is the oil pressure at idle within OEM specs?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Is blow-by present?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	MAJOR or MINOR <u>MINOR</u>
Do you see oil in the coolant?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Pressure check the cooling system	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<u>PASS</u> or FAIL
Is the clutch in good operating condition?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Rate (1-10): <u>4</u>

Brake Lining: Front R: 10% L: 20% Tag Axle R: \_\_\_\_\_ L: \_\_\_\_\_ 1st Axle R: 20% L: 20% 2nd Axle R: 20% L: 20%Tire Tread Percentage: Front: 20% Tag Axle: \_\_\_\_\_ 1st Axle: LF-10% Axle: LR-10% SUPER SINGLES  
RE 0% RR 0%

Comments: \_\_\_\_\_

Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10Comments: CK Eng Life ON.

Other Comments: \_\_\_\_\_

Inspector Print: BRANTDate: 10-03-23Inspector Signature: Jack Brant

\*\*\* This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way \*\*\*