

# Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

Red

Auction Date: Oct

Stock Number: 71000

Lot Number: \_\_\_\_\_

## HESS REPORT SHEET

\*\*\* ALL Trucks are For Sale AS IS, WHERE IS \*\*\*

\*\*\* This is NOT A WARRANTY! \*\*\*

286,069.9

Truck Type (Circle one): Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: \_\_\_\_\_

Year: 2004 Make: Mack Model: CV713 Vin #: 011442

Engine: Make: MACK Model: ? HP: ?

Odometer Reading: 286,071 ECM Reading: \_\_\_\_\_

| Task                                          | Yes                                 | No                                  | Comments                                    |
|-----------------------------------------------|-------------------------------------|-------------------------------------|---------------------------------------------|
| Does the Truck Start?                         | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | Jump Start: YES or <u>NO</u>                |
| Does the motor idle and run normally?         | <input checked="" type="checkbox"/> | <input type="checkbox"/>            |                                             |
| Does the truck have the Emission Deleted?     | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <u>IS NONE</u>                              |
| Does the Transmission operate in all gears?   | <input checked="" type="checkbox"/> | <input type="checkbox"/>            |                                             |
| Does the Air load in normal time?             | <input checked="" type="checkbox"/> | <input type="checkbox"/>            |                                             |
| Are there any fluid leaks?                    | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <u>OIL or COOLANT</u> MAJOR or <u>MINOR</u> |
| Do you see coolant in the oil?                | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |                                             |
| Is the oil pressure at idle within OEM specs? | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |                                             |
| Is blow-by present?                           | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | MAJOR or MINOR                              |
| Do you see oil in the coolant?                | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |                                             |
| Pressure check the cooling system             | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <u>PASS</u> or FAIL                         |
| Is the clutch in good operating condition?    | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | Rate (1-10): <u>4</u>                       |

Brake Lining: Front R: 70% 70% Tag Axle R: CAN'T SEE L: 100% 1st Axle R: 30% 30% 2nd Axle R: 50% 50%

Tire Tread Percentage: Front: 40% Tag Axle: 40% 1st Axle: 30% 2nd Axle: 60%

Comments: \_\_\_\_\_

Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10

Comments: \_\_\_\_\_

Other Comments: \_\_\_\_\_

Inspector Print: BRANT

Date: 10-02-23

Inspector Signature: Jack Brant

\*\*\* This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way \*\*\*