

# Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

WHITE

Auction Date: 10/13

Stock Number: 71754

Lot Number:

## HESS REPORT SHEET

\*\*\* ALL Trucks are For Sale AS IS, WHERE IS \*\*\*

\*\*\* This is NOT A WARRANTY! \*\*\*

Truck Type (Circle one): Sleeper / <u>Daycab</u> / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: _____			
Year: <u>2014</u> Make: <u>VOLVO</u> Model: <u>VNM</u> Vin #: <u>164589</u>			
Engine: Make: <u>VOLVO</u> Model: <u>D11</u> HP: <u>385</u>			
Odometer Reading: <u>170,014</u>		ECM Reading: _____	
Task	Yes	No	Comments
Does the Truck Start?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Jump Start: YES or <u>NO</u>
Does the motor idle and run normally?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Does the truck have the Emission Deleted?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Does the Transmission operate in all gears?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Does the Air load in normal time?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Are there any fluid leaks?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	OIL or COOLANT MAJOR or <u>MINOR</u>
Do you see coolant in the oil?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Is the oil pressure at idle within OEM specs?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Is blow-by present?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	MAJOR or MINOR
Do you see oil in the coolant?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Pressure check the cooling system	<input checked="" type="checkbox"/>	<input type="checkbox"/>	PASS or FAIL
Is the clutch in good operating condition?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Rate (1-10): _____
Brake Lining: Front: <u>CAN'T SEE</u> Tag Axle R: _____ L: _____ 1st Axle R: _____ L: _____ 2nd Axle R: <u>CAN'T SEE</u> L: _____			
Tire Tread Percentage: Front: <u>80%</u> Tag Axle: _____ 1st Axle: <u>LF 100%</u> 2nd Axle: <u>LR 20%</u> <u>RR 10%</u> <u>RR 40%</u>			
Comments: <u>LF 100%</u> <u>RF 20%</u> <u>RF 40%</u>			
Cosmetic Condition: Rate 1 2 3 <u>4</u> 5 6 7 8 9 10			
Comments: <u>LITTLE HOOD DAMAGE</u>			
Other Comments: <u>TWO CK Eng Lite ON. ABS &amp; TCS Lite ON.</u>			

Inspector Print: BRANT

Date: 10-08-23

Inspector Signature: Jack Brant

\*\*\* This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way \*\*\*

CAME IN TOO LATE, TO DRIVE!