## **Hess Auctioneers, LLC.**

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

Stock Number: 70607

Lot Number:

## **HESS REPORT SHEET**

\*\*\* ALL Trucks are For Sale AS IS, WHERE IS \*\*\*

Inis	IS NOT A WAR	RRANTY! ****	
Truck Type (Circle one): Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer/ Chassis / Other:			
Year: 2016 Make: NTERNATIONAL M	lodel: PRo 57	<u>ΓΑΩ</u> Vin #:	137533
Engine: Make: CUMMENS Model: ISX15 HP: 425			
Odometer Reading: 134 233 ECM Reading:			
Task <b>J</b> Ye		Con	ments
Does the Truck Start?	K	Jump Start: YES or NO	
Does the motor idle and run normally?	X		
Does the truck have the Emission Deleted?	X		*
Does the Transmission operate in all gears?			
Does the Air load in normal time?			
Are there any fluid leaks?	X	OIL or COOLANT	MAJOR or MINOR
Do you see coolant in the oil?	X		
Is the oil pressure at idle within OEM specs?	X		,
Is blow-by present?	X	MAJOR or MINOR	
Do you see oil in the coolant?	X		
Pressure check the cooling system	AV	PASS or FAIL	
Is the clutch in good operating condition?		Rate (1-10):	
Brake Lining: Front R. Logo Tag Axle R: L: 1st Axle R: 20% L: 20% 2nd Axle R: MAL: MA  Tire Tread Percentage: Front: 40% Tag Axle: 1st Axle: 60% 2nd Axle: MA Stock HXLE			
Tire Tread Percentage: Front: 40% Tag Axle:1st Axle:1st Axle:			
Comments:			
Cosmetic Condition: Rate 1 2 3 4 5 6 7 <b>8</b> 9 10			
Comments: CKEng Life ON.			
Other Comments:			
Inspector Print: BRANT Date: 10-09-23 Inspector Signature: Pack Browk			

\*\*\* This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way \*\*\*