

# Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

White

Auction Date: 10/13

Stock Number: 70610

Lot Number: 47

## HESS REPORT SHEET

\*\*\* ALL Trucks are For Sale AS IS, WHERE IS \*\*\*

\*\*\* This is NOT A WARRANTY! \*\*\*

Truck Type (Circle one): Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: \_\_\_\_\_

Year: 2015 Make: INTERNATIONAL Model: 4400 SBA Vin #: 682420

Engine: Make: NAVISTAR Model: 124L HP: 410

Odometer Reading: 167,218 ECM Reading: A 410

| Task                                          | Yes                                 | No                                  | Comments                             |
|-----------------------------------------------|-------------------------------------|-------------------------------------|--------------------------------------|
| Does the Truck Start?                         | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | Jump Start: YES or <u>NO</u>         |
| Does the motor idle and run normally?         | <input checked="" type="checkbox"/> | <input type="checkbox"/>            |                                      |
| Does the truck have the Emission Deleted?     | <input type="checkbox"/>            | <input checked="" type="checkbox"/> |                                      |
| Does the Transmission operate in all gears?   | <input type="checkbox"/>            | <input type="checkbox"/>            |                                      |
| Does the Air load in normal time?             | <input checked="" type="checkbox"/> | <input type="checkbox"/>            |                                      |
| Are there any fluid leaks?                    | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | OIL or COOLANT MAJOR or <u>MINOR</u> |
| Do you see coolant in the oil?                | <input checked="" type="checkbox"/> | <input type="checkbox"/>            |                                      |
| Is the oil pressure at idle within OEM specs? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            |                                      |
| Is blow-by present?                           | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | MAJOR or MINOR                       |
| Do you see oil in the coolant?                | <input checked="" type="checkbox"/> | <input type="checkbox"/>            |                                      |
| Pressure check the cooling system             | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <u>PASS</u> or FAIL                  |
| Is the clutch in good operating condition?    | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | Rate (1-10): _____                   |

Brake Lining: Front R: 70% L: 70% Tag Axle R: \_\_\_\_\_ L: \_\_\_\_\_ 1<sup>st</sup> Axle R: 70% L: 70% 2<sup>nd</sup> Axle R: 70% L: 70%

Tire Tread Percentage: Front: 70% Tag Axle: \_\_\_\_\_ 1<sup>st</sup> Axle: 70% 2<sup>nd</sup> Axle: 60%

Comments:

Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10

Comments:

Little Hood Damage.

Other Comments:

Inspector Print: BRANT

Date: 10-09-23

Inspector Signature: Jack Brant

\*\*\* This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way \*\*\*

CAME IN TOO LATE, TOO DRIVE!