

Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

B102

Auction Date: OCT
Stock Number: 71574
Lot Number: 212

HESS REPORT SHEET

*** ALL Trucks are For Sale AS IS, WHERE IS ***

*** This is NOT A WARRANTY! ***

Truck Type (Circle one) <u>Sleeper</u> / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: _____			
Year: <u>2016</u> Make: <u>Western Star</u> Model: <u>4900</u> Vin #: <u>1HF5019</u>			
Engine: Make: <u>DET</u> Model: <u>?</u> HP: <u>?</u>			
Odometer Reading: <u>752,232</u> ECM Reading: _____			
Task	Yes	No	Comments
Does the Truck Start?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Jump Start: YES or <u>NO</u>
Does the motor idle and run normally?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Does the truck have the Emission Deleted?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Does the Transmission operate in all gears?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Does the Air load in normal time?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Are there any fluid leaks?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<u>OIL or COOLANT</u> MAJOR or <u>MINOR</u>
Do you see coolant in the oil?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Is the oil pressure at idle within OEM specs?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Is blow-by present?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	MAJOR or MINOR
Do you see oil in the coolant?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Pressure check the cooling system	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>PASS or FAIL</u>
Is the clutch in good operating condition?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Rate (1-10): _____
Brake Lining: Front R: <u>50%</u> L: <u>60%</u> Tag Axle R: _____ L: _____ 1st Axle R: <u>30%</u> L: <u>30%</u> 2nd Axle R: <u>80%</u> L: <u>80%</u>			
Tire Tread Percentage: Front: <u>40%</u> Tag Axle: _____ 1st Axle: <u>20%</u> 2nd Axle: <u>LRI-10% RRI</u> <u>LRO-70% RRO</u> / <u>20%</u>			
Comments: _____			
Cosmetic Condition: Rate 1 2 3 4 5 <u>6</u> 7 8 9 10			
Comments: _____			
Other Comments: _____			

Inspector Print: BRANT

Date: 10-09-23

Inspector Signature: Jack Brant

*** This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way ***

CAME IN TOO LATE, TOO DRIVE!