

# Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

Auction Date: Oct

Stock Number: 71588

Lot Number: 214

## HESS REPORT SHEET

\*\*\* ALL Trucks are For Sale AS IS, WHERE IS \*\*\*

\*\*\* This is NOT A WARRANTY! \*\*\*

Truck Type (Circle one): Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: \_\_\_\_\_

Year: 2016 Make: Mack Model: CXUG13 Vin #: 053452

Engine: Make: MACK Model: MP8 HP: 445

Odometer Reading: 575,028 ECM Reading: \_\_\_\_\_

Task	Yes	No	Comments
Does the Truck Start?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Jump Start: YES or NO <u>NO</u>
Does the motor idle and run normally?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Does the truck have the Emission Deleted?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Does the Transmission operate in all gears?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Does the Air load in normal time?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Are there any fluid leaks?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OIL or COOLANT MAJOR or MINOR <u>MINOR</u>
Do you see coolant in the oil?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Is the oil pressure at idle within OEM specs?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Is blow-by present?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	MAJOR or MINOR
Do you see oil in the coolant?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Pressure check the cooling system	<input checked="" type="checkbox"/>	<input type="checkbox"/>	PASS or FAIL <u>PASS</u>
Is the clutch in good operating condition?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Rate (1-10): _____

Brake Lining: Front R: 80% L: 80% Tag Axle R: \_\_\_\_\_ L: \_\_\_\_\_ 1st Axle R: 30% L: 30% 2nd Axle R: 30% L: 30%

Tire Tread Percentage: Front: 50% Tag Axle: \_\_\_\_\_ 1st Axle: 50% 2nd Axle: 40%

Comments:

Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10

Comments:

ck Eng Lite ON

Other Comments: \_\_\_\_\_

Inspector Print: BRA NT

Date: 10-09-23

Inspector Signature: Jack Brant

\*\*\* This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way \*\*\*

CAME IN TOO LATE, TOO DRIVE!