

Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

White

Auction Date: Oct

Stock Number: 71571

Lot Number: 217

HESS REPORT SHEET

*** ALL Trucks are For Sale AS IS, WHERE IS ***

*** This is NOT A WARRANTY! ***

Truck Type (Circle one): <u>Sleeper</u> / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: _____			
Year: <u>2016</u> Make: <u>Volvo</u> Model: _____ Vin #: <u>191855</u>			
Engine: Make: <u>Volvo</u> Model: <u>D13</u> HP: <u>455</u> <u>941855</u>			
Odometer Reading: <u>657,981</u>		ECM Reading: _____	
Task	Yes	No	Comments
Does the Truck Start?		X	Jump Start <u>YES</u> or NO
Does the motor idle and run normally?	X	X	
Does the truck have the Emission Deleted?		X	
Does the Transmission operate in all gears?		X	
Does the Air load in normal time?	X	X	
Are there any fluid leaks?	X	X	OIL or COOLANT MAJOR or MINOR <u>MINOR</u>
Do you see coolant in the oil?	X	X	
Is the oil pressure at idle within OEM specs?	X	X	
Is blow-by present?	X	X	MAJOR or MINOR
Do you see oil in the coolant?	X	X	
Pressure check the cooling system	X	X	PASS or FAIL
Is the clutch in good operating condition?	X	X	Rate (1-10): _____ <u>Automatic</u>
Brake Lining: Front: <u>CAN'T SEE</u> L: _____ Tag Axle R: _____ L: _____ 1st Axle R: _____ L: _____ 2nd Axle R: _____ L: _____ <u>CAN'T SEE</u>			
Tire Tread Percentage: Front: <u>40%</u> Tag Axle: _____ 1st Axle: <u>LFI-20%</u> 2nd Axle: <u>LFI-20%</u> <u>LRO-50%</u> <u>RFI-30%</u> <u>LRI-90%</u> <u>RRI-20%</u> <u>RRO-50%</u>			
Comments: _____			
Cosmetic Condition: Rate 1 2 3 4 5 6 <u>7</u> 8 9 10			
Comments: <u>BOTH AIR FOLDS BEHIND BUNK ARE Damaged</u>			
Other Comments: <u>ck Eng lite ON.</u>			

Inspector Print: BRANT

Date: 10-09-23

Inspector Signature: Jack Brant

*** This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way ***

CAME IN TOO LATE, TOO DRIVE!