

# Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

WHITE

Auction Date: 10/13

Stock Number: 70131

Lot Number: 231

## HESS REPORT SHEET

\*\*\* ALL Trucks are For Sale AS IS, WHERE IS \*\*\*

\*\*\* This is NOT A WARRANTY! \*\*\*

Truck Type (Circle one): <u>Sleeper</u> / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: _____			
Year: <u>2016</u> Make: <u>Freightliner</u> Model: <u>CASCADIA</u> Vin #: <u>GZ2765</u>			
Engine: Make: <u>DET</u> Model: <u>?</u> HP: <u>?</u>			
Odometer Reading: <u>834,429</u> ECM Reading: _____			
Task	Yes	No	Comments
Does the Truck Start?	<u>X</u>		Jump Start: YES or <u>NO</u>
Does the motor idle and run normally?	<u>X</u>		
Does the truck have the Emission Deleted?	<u>X</u>	<u>X</u>	
Does the Transmission operate in all gears?			
Does the Air load in normal time?	<u>X</u>		
Are there any fluid leaks?	<u>X</u>		<u>OIL</u> or COOLANT MAJOR or <u>MINOR</u>
Do you see coolant in the oil?	<u>X</u>	<u>X</u>	
Is the oil pressure at idle within OEM specs?	<u>X</u>		
Is blow-by present?	<u>X</u>	<u>X</u>	MAJOR or MINOR
Do you see oil in the coolant?	<u>X</u>	<u>X</u>	
Pressure check the cooling system	<u>X</u>		PASS or FAIL
Is the clutch in good operating condition?			Rate (1-10): _____
Brake Lining: Front R: <u>80%</u> L: <u>80%</u> Tag Axle R: _____ L: _____ 1st Axle R: <u>CAN'T SEE</u> L: _____ 2nd Axle R: _____ L: _____			
Tire Tread Percentage: Front: <u>80%</u> Tag Axle: _____ 1st Axle: <u>40%</u> 2nd Axle: <u>50%</u> LFO/20% RFI - 80% RFO - 40%			
Comments: _____			
Cosmetic Condition: Rate 1 2 3 4 <u>5</u> 6 7 8 9 10			
Comments: <u>Little Hood Damage</u>			
Other Comments: _____			

Inspector Print: BRANT

Date: 10-09-23

Inspector Signature: Jack Brant

\*\*\* This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way \*\*\*

CAME IN TOO LATE, TOO DRIVE!