

Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

Blue

Auction Date: OCT
Stock Number: 71595
Lot Number: 256

HESS REPORT SHEET

*** ALL Trucks are For Sale AS IS, WHERE IS ***

*** This is NOT A WARRANTY! ***

Truck Type (Circle one): <u>Sleeper</u> / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: _____			
Year: <u>2014</u> Make: <u>Freightliner</u> Model: <u>SA125SLP</u> Vin #: <u>FL4217</u>			
Engine: Make: <u>DET</u> Model: <u>DD15</u> HP: <u>505</u>			
Odometer Reading: <u>953,916</u> ECM Reading: _____			
Task	Yes	No	Comments
Does the Truck Start?		X	Jump Start: <u>YES</u> or NO
Does the motor idle and run normally?	X		
Does the truck have the Emission Deleted?		X	
Does the Transmission operate in all gears?			
Does the Air load in normal time?	X		
Are there any fluid leaks?	X		OIL or COOLANT MAJOR or MINOR
Do you see coolant in the oil?		X	
Is the oil pressure at idle within OEM specs?	X		
Is blow-by present?		X	MAJOR or MINOR
Do you see oil in the coolant?		X	
Pressure check the cooling system	X		PASS or FAIL
Is the clutch in good operating condition?			Rate (1-10): _____
Brake Lining: Front R: <u>70%</u> L: <u>70%</u> Tag Axle R: _____ L: _____ 1st Axle R: <u>50%</u> L: <u>50%</u> 2nd Axle R: <u>100%</u> L: <u>100%</u>			
Tire Tread Percentage: Front: <u>100%</u> Tag Axle: _____ 1st Axle: <u>LFT-100% RFT-100%</u> 2nd Axle: _____			
Comments: <u>LFO-20% RFO-20%</u> <u>LRT-100% RRT-100%</u> <u>LRO-100% RRO-100%</u>			
Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10			
Comments: <u>Hood & Bumper Damage.</u>			
Other Comments: <u>CK Eng lite on.</u>			

Inspector Print: BRANT

Date: 10-09-23

Inspector Signature: Jack Brant

*** This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way ***

CAME IN TOO LATE, TOO DRIVE!