

Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

BLUE

Auction Date: 10/13

Stock Number: 71580

Lot Number: 272

HESS REPORT SHEET

*** ALL Trucks are For Sale AS IS, WHERE IS ***

*** This is NOT A WARRANTY! ***

Truck Type (Circle one): <u>Sleeper</u> / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: _____			
Year: <u>2012</u> Make: <u>VOLVO</u> Model: <u>VNL</u> Vin #: <u>555342</u>			
Engine: Make: <u>VOLVO</u> Model: <u>D16</u> HP: <u>500</u>			
Odometer Reading: <u>247,377</u> ECM Reading: _____			
Task	Yes	No	Comments
Does the Truck Start?		X	Jump Start: YES or NO
Does the motor idle and run normally?	X		
Does the truck have the Emission Deleted?		X	
Does the Transmission operate in all gears?		X	
Does the Air load in normal time?	X		
Are there any fluid leaks?	X		OIL or COOLANT MAJOR or MINOR
Do you see coolant in the oil?		X	
Is the oil pressure at idle within OEM specs?	X		
Is blow-by present?		X	MAJOR or MINOR
Do you see oil in the coolant?		X	
Pressure check the cooling system	X		PASS or FAIL
Is the clutch in good operating condition?			Rate (1-10): _____
Brake Lining: Front R: <u>40%</u> L: <u>20%</u> Tag Axle R: _____ L: _____ 1st Axle R: <u>60%</u> L: <u>60%</u> 2nd Axle R: <u>80%</u> L: <u>80%</u>			
Tire Tread Percentage: Front <u>RF - 10%</u> Tag Axle: _____ 1st Axle: <u>30%</u> 2nd Axle: <u>20%</u>			
Comments: <u>RF - 20%</u>			
Cosmetic Condition: Rate 1 2 3 4 5 <u>6</u> 7 8 9 10			
Comments:			
Other Comments:			

Inspector Print: BRANT

Date: 10-09-23

Inspector Signature: Jack Brant

*** This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way ***

CAME IN TOO LATE, TOO DRIVE!