

Kenworth Tractor #52

Registration Plate Number
Vehicle Year 2016
Make Kenworth
Tire Size

Inspection Due Dates 5/31/2018
Maintenance Due Date Every 10,000 Miles

Inspection Completed Date 5/13/2022
 5/7/2021
 5/15/2020
 5/6/2019
 6/5/2018
 1/31/2018
 5/4/2017
 10/18/2016
 5/23/2016
 12/15/2015

Maintenance Completed Date	3/4/2023 455,593 (Oil)
(Lube & Adjusted Brakes)	12/28/2022 446,959 (Lube)
10/16/2022	435,287 (Oil)
8/22/2022	422,505 (lube)
7/13/2022	411,923 (oil)
5/13/2022	400,395 (lube)
2/25/2022	387,681 (oil)
1/7/2022	377,266 (lube)
11/6/2021	366,614 (oil)
3/13/2021	357,254 (lube)
1/11/2021	346,677 (oil)
10/30/2020	335,569 (lube)
7/7/2020	321,774 (OIL)
4/29/2020	312,234 (lube)
3/3/2020	302,465 (Oil)
1/9/2020	292,274 (lube)
11/20/2019	282,452
9/12/2019	272,367
4/30/2019	251,759 (lube)
2/26/2019	241031 (oil)
11/8/2018	219,797
8/24/2018	208,645
3/28/2016	188,381
1/31/2018	177,721
9/25/2017	155,139
7/26/2017	144,040
5/11/2017	133,671
3/22/2017	123548 (lube)
1/27/2017	112,830
12/15/2016	104,526
8/19/2016	80,666

6/30/2016	70,700
5/23/2016	62,719
2/29/19	49,360
12/15/2015	33,117
9/24/2015	17,484

Repair Completion Date

	3/23/2023	Right front marker light inop Found Bad Bulb and bad wire. Fixed by jumpin
	3/4/2023	Service (Oil) Check Sheet
	2/15/2023	Replace right rear outside tire with used one
	2/9/2023	Replace Lower Radiator Clamp
	1/26/2023	Repalce R/F/I Tire with used Tire
	12/28/2022	Service (Lube) Check Sheet Replaced Bolts in Bell Housing Replaced Cab Air Filter
	12/24/2022	Replace fuel filters Thaw suspension valve
	12/24/2022	Right Front Inside Drive Tire Low, Found nail in tire and plugged tire. Aired I
	12/12/2022	Replace Air Compressor
	11/12/2022	Replace Clutch and ECA Replace Rear Main Seal Replace Exhaust Gaskets and Elbow after Flex Pipe Replace Pilot Bearing Had Flywheel turned at Cumberland Truck Parts Replace Batteries
	10/16/2022	Service-Oil Check Sheet Repair Air Leak on Air Supply at left front frame rail Service Air Dryer Service HydraPak Repalce Exhaust Bellows
	9/6/2022	Intermittent ABS light only while wet. Removed multiple plugs and checked w Air leak on signal line. Replaced bad push connect fitting
	9/12/2022	ABS light back on but went off again, no active codes. Doing full pin our at br Trailer tail light wire broken off, right after plug in frame rail fixed.
	8/22/2022	Service - lube Check sheet
	7/13/2022	Service - oil Check sheet
	7/12/2022	Replace washer bottle
	5/31/2022	Replace axle gasket right front rear
	5/23/2022	Replace fan air solenoid Tighten front axle, axle nuts
	6/13/2022	Replace leaking EGR cooler Replace exhaust manifold gaskets Replace thermostat Replace coolant and flush system Replace outlet nox sensor
	5/13/2022	Service - lube Check sheet Replace exhaust flex pipe

	Replace steer tires
	PA State Inspection Exp 6/23
2/25/2022	Service - oil
	Check sheet
	Rotate steer tires
	Replace left front drive "C" spring
2/15/2022	Fixed oil leak @ hydro pak - suction line was leaking, installed new clamp
2/5/2022	Wouldn't build air, replaced governor and air dryer filter and purge valve
1/7/2022	Service - lube
	Check sheet
	Replace C spring on L/F and R/R axle
11/6/2021	Service - oil
	Check sheet
	Service hydra pak
5/7/2021	Replace all drive brakes
	Replace all C springs
	Replace cabin air filter
	Replace drive tires
	Replace radiator core
	Replace broken arm rest
	Clean def doser
	PA State Inspection exp 6/22
3/25/2021	Update transmission ECU
3/9/2021	Replace hill assist valve
3/13/2021	Service - lube
	Check sheet
	Replace steer axle brakes
2/6/2021	Replace DOC
	Replace exhaust pressure sensor
	Adjusted fifth wheel
1/22/2021	Fix bracket to hold hydro hoses behind cab
1/13/2021	Replaced shocks on drives, steers, and cab shocks
	Replace cab leveling valve
1/11/2021	Service - oil
	Check sheet
	Replace carrier bearing
11/13/2020	Replace fuel filters
11/4/2020	Replace turbo actuator
10/30/2020	Replace steer tires
	Service - lube
	Check sheet
	Replace drive brakes
	Rotate drive tires
	Replace PTO solenoid valve
	Tighten left 1/2 fender
10/1/2020	Replace intake nox sensor
8/3/2020	Replace front blower motor
7/7/2020	Service - oil
	Check sheet
	Replace right top heat shield clamp
	Clean connection for tablet charger
	Replace rusted radiator lower pipe
	Replace rusted coolant manifold
5/26/2020	Replace tablet for ELD
5/15/2020	State Inspection

	Rebuild air dryer
	Replace hydraulic filter
5/7/2020	Replace windshield washer fluid tank
	Replace air tank straps
4/29/2020	Service (lube)
	Check sheet
	Replace leaking left front wheel seal
	Replace leaking right front wheel seal
	Replace windshield wipers
	Replace power steering resevoir cap
	Replace passenger side tie rod end
3/3/2020	Service - oil
	Check sheet
	Repair air leak under cab
	Replace leaking left front wheel seal
	Replace right hood shock
	Replace broken driverside heat shield clamp
	Replace driver side antenna with used antenna
	Replace right rear maxi chamber
2/20/2020	Replace belts and tensioners
2/17/2020	Replace fuel filters
	Replace power steering resevoir cap
	Replace left front marker bulb
1/14/2020	Replace right headlight assembly
1/9/2020	Service (lube)
	Check sheet
	Replace left rear maxi chamber
	Replace leaking right rear axle flange gasket
12/13/2019	Pull bumper out on right front from wreck
11/20/2019	Service oil
	Check sheet
	Tighten loose hose clamps - coolant
	Repalce broken right front drive maxi
11/1/2019	Replace brakes and rotor on drive axles
10/24/2019	Replace low beam bulb
	Repair coolant leak at heater core
10/14/2019	Replaced leveling valve
10/9/2019	Replaced batteries
9/16/2019	Replaced steer axle brakes and rotors
9/12/2019	Service lube
	Check sheet
	Replace leaking left rear air bag
	Tighten left 1/4 fender
	Replace broken exhaust shield clamps
8/27/2019	Replace Drive tires, put tires on from last winter
8/16/2019	Update engine ECM
8/7/2019	Replace wiper blades
8/1/2019	Replace torque arms on both rears
7/9/2019	PM/service truck
	Check sheets
	Installed card doe electronic dump valve
	Replace wiper blades
6/26/2019	Repair right rear inside tire
	Air in all tires
6/3/2019	Replaced block heater cord

5/17/2019	Replaced hydro pack filter and oil Replaced bulb in right front corner Repaired coolant leak at head firewall Repair wire connection for tail lights
5/6/2019	Replace dash valve Replace air dryer and purge valve Tighten half fender brake and left side PA State Inspection
4/30/2019	Pm/truck (lube) Check hard card
3/24/2019	Repair compressor discharge line to air dryer
2/26/2019	Service (oil) Check sheet Brake chamber left front rear Tighten left half fender
1/22/2019	Replace black heater cord
1/3/2019	Service Check sheet
11/8/2018	Service (oil) Check sheet Fix anti-freeze leak at tranny cooler
10/17/2018	Replace steer tires
9/18/2018	Replace drive tires Replace steer tires and put Balaance in tires on steer axle
9/14/2018	Grease fifth wheel jaws and check for wear
8/24/2018	Check sheet
8/14/2018	Fix air leak at dryer Rebuild dryer and purge valve
6/20/2018	Replace cab filter
6/19/2018	Upgrade software in dash using eportal
6/18/2018	PM
6/4/2018	Replace left headlight
6/1/2018	Staighthen out bumper on driver side front
4/21/2018	Fix wiring for tail lights
3/28/2016	Check sheet Adjusted brakes Replace air cleaner
2/23/2018	Replace wiper blades
2/8/2018	Replace ambient temperature sensor or driver side mirror
2/1/2018	Replace front brakes Rotate stear tires Continued on Next Page

Kenworth Tractor #52

Repair Completion Date
Cont

1/31/2018	Service Check sheet Adj. brakes Replace DEF filter
11/26/2017	Service Check sheet Adj. brakes

	Replace both drive axle brakes
	Rotate drive tires
	Replace right front drive axle and air bag for suspension
9/25/2017	check sheet
	Adj brakes
	Replace cab air filter
8/23/2017	Rebuild air dryer, check for air leak
8/3/2017	Change engine breather element
	Change exhaust fluid filter
7/31/2017	Replace steer tires
	Replace wipers
	Add anti freeze
7/6/2017	Rotate drive tires
5/11/2017	PM
	Service hydro pak
4/13/2017	Repair door light and dome lights
2/10/2017	Replace LR caliper
1/27/2017	Check sheet
	Replace brakes drive axles
	Replace drive tires
12/15/2016	PM
11/3/2016	Replace wiper blades
	Check fault codes
10/18/2016	Replace wiper 22"
8/19/2016	PM
8/12/2016	Replace steer tires
	checked squeaking noise
	took to kenworth and picked up
6/30/2016	PM
5/23/2016	Check sheet
4/18/2016	Repair rear outside drive tire
2/29/2016	Check Batteries
1/22/2016	Repair air lines
12/15/2015	Check sheet
9/24/2015	Check sheet
8/24/2015	Install dura grips
7/7/2015	Install half fenders
	Wire work lights