

**Hess Auctioneers, LLC.**

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

Black

Auction Date: DecStock Number: 72715

Lot Number: \_\_\_\_\_

**HESS REPORT SHEET**

\*\*\* ALL Trucks are For Sale AS IS, WHERE IS \*\*\*

\*\*\* This is NOT A WARRANTY! \*\*\*

531,653

Truck Type (Circle one): Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: \_\_\_\_\_Year: 2019 Make: Freightliner Model: Cascadia Vin #: 1KP3585Engine: Make: DET Model: DD15 HP: 505Odometer Reading: 531,653 ECM Reading: \_\_\_\_\_

Task	Yes	No	Comments
Does the Truck Start?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Jump Start: YES or <u>NO</u>
Does the motor idle and run normally?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Does the truck have the Emission Deleted?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Does the Transmission operate in all gears?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Does the Air load in normal time?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Are there any fluid leaks?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OIL or COOLANT MAJOR or <u>MINOR</u>
Do you see coolant in the oil?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Is the oil pressure at idle within OEM specs?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Is blow-by present?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	MAJOR or MINOR
Do you see oil in the coolant?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Pressure check the cooling system	<input checked="" type="checkbox"/>	<input type="checkbox"/>	PASS or FAIL
Is the clutch in good operating condition?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Rate (1-10): <u>Automatic</u>

(DESC) CAN'T SEE Brake Lining: Front R: \_\_\_\_\_ L: \_\_\_\_\_ Tag Axle R: \_\_\_\_\_ L: \_\_\_\_\_ 1st Axle R: \_\_\_\_\_ L: \_\_\_\_\_ 2nd Axle R: \_\_\_\_\_ L: \_\_\_\_\_ (DESC)

Tire Tread Percentage: Front: 80% Tag Axle: \_\_\_\_\_ 1st Axle: 100% 2nd Axle: 100%

Comments: (CAPS)

Cosmetic Condition: Rate 1 2 3 4 5 6 8 9 10

Comments: DRIVER SEAT, TAPE UP!

Other Comments: STONE CHIP, MIDDLE OF WINDSHIELD.Inspector Print: BRANTDate: 11-6-23Inspector Signature: Jack Brant

\*\*\* This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way \*\*\*