

Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

White

Auction Date: 12/8
Stock Number: 72754
Lot Number: _____

HESS REPORT SHEET

*** ALL Trucks are For Sale AS IS, WHERE IS ***

*** This is NOT A WARRANTY! ***

288,787

Truck Type (Circle one): Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: _____

Year: 2015 Make: Freightliner Model: AS Gdia Vin #: GA2051

Engine: Make: DET Model: DD13 HP: 500

Odometer Reading: 288,787 ECM Reading: _____

Task	Yes	No	Comments
Does the Truck Start?	X		Jump Start: YES or NO
Does the motor idle and run normally?	X	X	
Does the truck have the Emission Deleted?		X	
Does the Transmission operate in all gears?	X	X	
Does the Air load in normal time?	X		
Are there any fluid leaks?	X		OIL or COOLANT MAJOR or MINOR
Do you see coolant in the oil?		X	
Is the oil pressure at idle within OEM specs?	X		
Is blow-by present?	X	X	MAJOR or MINOR
Do you see oil in the coolant?		X	
Pressure check the cooling system	X		PASS or FAIL
Is the clutch in good operating condition?	X		Rate (1-10): <u>4</u>
CAN'T-SEE. Brake Lining: Front R: _____ L: _____ Tag Axle R: _____ L: _____ 1st Axle R: <u>80%</u> L: _____ 2nd Axle R: _____ L: _____ CAN'T-SEE			
Tire Tread Percentage: Front <u>LF-80%</u> Tag Axle: _____ 1st Axle: <u>LF-70%</u> 2nd Axle: <u>LRI-30%</u> <u>LRO-70%</u>			
Comments: <u>RF-30%</u> <u>LF0-40%</u> <u>RFE-40%</u> <u>RRI-40%</u> <u>RR0-40%</u>			
Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10			
Comments: <u>Little Hood Damage, DRIVER SIDE BTM.</u>			
Other Comments: _____			

Inspector Print: BRANT

Date: 11-13-23

Inspector Signature: Jack Brant

*** This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way.***