

# Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

Auction Date: 12/8

Stock Number: 72744

Lot Number: \_\_\_\_\_

## HESS REPORT SHEET

\*\*\* ALL Trucks are For Sale AS IS, WHERE IS \*\*\*

\*\*\* This is NOT A WARRANTY! \*\*\*

Truck Type (Circle one): Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: \_\_\_\_\_

Year: 2016 Make: Freightliner Model: Cascadia Vin #: HT2656

Engine: Make: DET Model: DD13 HP: 300

Odometer Reading: 793,143 ECM Reading: \_\_\_\_\_

Task	Yes	No	Comments
Does the Truck Start?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Jump Start: YES or <u>NO</u>
Does the motor idle and run normally?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Does the truck have the Emission Deleted?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
Does the Transmission operate in all gears?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Does the Air load in normal time?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Are there any fluid leaks?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>OIL</u> or COOLANT MAJOR or <u>MINOR</u>
Do you see coolant in the oil?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Is the oil pressure at idle within OEM specs?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Is blow-by present?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	MAJOR or MINOR
Do you see oil in the coolant?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Pressure check the cooling system	<input checked="" type="checkbox"/>	<input type="checkbox"/>	PASS or <u>FAIL</u>
Is the clutch in good operating condition?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Rate (1-10): <u>4</u>

CAN'T SEE (DISC) CAN'T SEE (DISC)  
Brake Lining: Front R: \_\_\_\_\_ L: \_\_\_\_\_ Tag Axle R: \_\_\_\_\_ L: \_\_\_\_\_ 1<sup>st</sup> Axle R: \_\_\_\_\_ L: \_\_\_\_\_ 2<sup>nd</sup> Axle R: NA L: NA

Tire Tread Percentage: Front: 70% Tag Axle: \_\_\_\_\_ 1<sup>st</sup> Axle: \_\_\_\_\_ 2<sup>nd</sup> Axle: NA Single AXLE

Comments: LRI & LRO - 30%  
RRI & RRO > 10%

Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10

Comments: BUMPER GUARD IN FRONT OF

Other Comments: BUMPER IS DAMAGE!

Inspector Print: BRANT

Date: 11-27-23

Inspector Signature: Jack Brant

\*\*\* This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way \*\*\*