

# Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

White

Auction Date: Feb  
Stock Number: 74 244  
Lot Number: \_\_\_\_\_

## HESS REPORT SHEET

\*\*\* ALL Trucks are For Sale AS IS, WHERE IS \*\*\*

\*\*\* This is NOT A WARRANTY! \*\*\*

Truck Type (Circle one): <u>Sleeper</u> / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: _____			
Year: <u>2017</u> Make: <u>International</u> Model: <u>ProStar</u> Vin #: <u>714051</u>			
Engine: Make: <u>Detroit</u> Model: <u>DD13</u> HP: _____			
Odometer Reading: <u>179,987</u>		ECM Reading: <u>179,987</u>	
Task	Yes	No	Comments
Does the Truck Start?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Jump Start: YES or <u>NO</u>
Does the motor idle and run normally?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Does the truck have the Emission Deleted?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Does the Transmission operate in all gears?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Does the Air load in normal time?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Are there any fluid leaks?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>Oil</u> or COOLANT MAJOR or MINOR
Do you see coolant in the oil?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Is the oil pressure at idle within OEM specs?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Is blow-by present?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	MAJOR or MINOR
Do you see oil in the coolant?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Pressure check the cooling system	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>PASS</u> or FAIL
Is the clutch in good operating condition?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Rate (1-10): _____
Brake Lining: Front R: <u>DISC</u> L: _____ Tag Axle R: _____ L: _____ 1st Axle R: <u>DISC</u> L: _____ 2nd Axle R: <u>DISC</u> L: _____			
Tire Tread Percentage: Front: <u>50/50</u> Tag Axle: _____ 1st Axle: <u>40/40</u> 2nd Axle: <u>40/40</u>			
Comments: _____			
Cosmetic Condition: Rate 1 2 3 4 5 <u>6</u> 7 8 9 10			
Comments: <u>Check Engine Light</u>			
Other Comments: _____			

Inspector Print: STEVE VIVIANO

Date: 1-23-24

Inspector Signature: [Signature]

\*\*\* This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way \*\*\*