

Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

White

Auction Date: Feb

Stock Number: 75175

Lot Number:

HESS REPORT SHEET

*** ALL Trucks are For Sale AS IS, WHERE IS ***

*** This is NOT A WARRANTY! ***

Truck Type (Circle one): Sleeper / <u>Daycab</u> / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other:			
Year: <u>2017</u>		Make: <u>Norve</u>	
Model: <u>VNL</u>		Vin #: <u>981744</u>	
Engine: Make: <u>Volvo</u>		Model: <u>D13</u>	
HP: <u>425</u>			
Odometer Reading: <u>653,596</u>		ECM Reading: <u>653,598</u>	
Task	Yes	No	Comments
Does the Truck Start?	<u>X</u>		Jump Start: YES or <u>NO</u>
Does the motor idle and run normally?	<u>X</u>		
Does the truck have the Emission Deleted?		<u>X</u>	
Does the Transmission operate in all gears?	<u>X</u>		
Does the Air load in normal time?	<u>X</u>		
Are there any fluid leaks?	<u>X</u>		<u>OIL</u> or COOLANT MAJOR or <u>MINOR</u>
Do you see coolant in the oil?		<u>X</u>	
Is the oil pressure at idle within OEM specs?	<u>X</u>		
Is blow-by present?	<u>X</u>		MAJOR or <u>MINOR</u>
Do you see oil in the coolant?		<u>X</u>	
Pressure check the cooling system	<u>X</u>		PASS or <u>FAIL</u>
Is the clutch in good operating condition?	<u>ACT</u>		Rate (1-10):
Brake Lining: Front R: <u>50</u> L: <u>50</u> Tag Axle R: L: 1 st Axle R: <u>40</u> L: <u>40</u> 2 nd Axle R: <u>40</u> L: <u>40</u>			
Tire Tread Percentage: Front <u>50/50</u> Tag Axle: 1 st Axle: <u>40/40</u> 2 nd Axle: <u>30/30</u>			
Comments:			
Cosmetic Condition: Rate 1 2 3 4 <u>6</u> 7 8 9 10			
Comments: <u>Check Engine Light on / DPR Light</u>			
Other Comments:			

Inspector Print: JOE KINASE

Date: 1-24-24

Inspector Signature: Joe Kinase

*** This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way ***