

Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

Auction Date: 6/14

Stock Number: 77906

Lot Number: _____

HESS REPORT SHEET

*** ALL Trucks are For Sale **AS IS, WHERE IS** ***

*** This is **NOT A WARRANTY!** ***

Truck Type (Circle one): <u>Sleeper</u> / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: _____			
Year: <u>2016</u> Make: <u>International</u> Model: <u>PRO STAR 122</u> Vin #: <u>750893</u>			
Engine: Make: <u>Cummins</u> Model: <u>415</u> HP: <u>425</u>			
Odometer Reading: <u>812,368</u> ECM Reading: <u>38,313</u>			
Task	Yes	No	Comments
Does the Truck Start?	<u>X</u>		Jump Start: YES or <u>NO</u>
Does the motor idle and run normally?	<u>X</u>		
Does the truck have the Emission Deleted?	<u>X</u>		
Does the Transmission operate in all gears?	<u>X</u>		
Does the Air load in normal time?	<u>X</u>		
Are there any fluid leaks?	<u>X</u>		<u>OIL</u> or COOLANT MAJOR or <u>MINOR</u>
Do you see coolant in the oil?		<u>X</u>	
Is the oil pressure at idle within OEM specs?	<u>X</u>		
Is blow-by present?	<u>X</u>		MAJOR or <u>MINOR</u>
Do you see oil in the coolant?	<u>X</u>		
Pressure check the cooling system	<u>X</u>		<u>PASS</u> or FAIL
Is the clutch in good operating condition?	<u>X</u>		Rate (1-10): <u>5</u>
Brake Lining: Front R: <u>30</u> L: <u>30</u> Tag Axle R: _____ L: _____ 1 st Axle R: <u>30</u> L: <u>30</u> 2 nd Axle R: <u>40</u> L: <u>40</u>			
Tire Tread Percentage: Front: <u>50/50</u> Tag Axle: _____ 1 st Axle: <u>40/30</u> 2 nd Axle: <u>30/40</u>			
Comments: _____			
Cosmetic Condition: Rate 1 2 3 4 <u>6</u> 6 7 8 9 10			
Comments: <u>CEL on</u>			
Other Comments: _____			

Inspector Print: Steve Kincaid

Date: 5-17-24

Inspector Signature: Steve Kincaid

*** This report is performed as a guide for our buyers. This report is **NOT** a warranty and **DOES NOT** in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way ***