Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

whiTe

Phone: 1-866-511-2493 Fax: 717-427-1665 Stock Number: 77984

Auction Date:

Lot Number:

HESS REPORT SHEET

*** ALL Trucks are For Sale AS IS, WHERE IS *** *** This is **NOT A WARRANTY!** ***

Truck Type (Circle one): Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer/ Chassis / Other:				
Year: 2016 Make: Volvo	Model:	VNL	Vin #:	967551
Year: 2016 Make: Volvo Model: VNL Vin #: 967551 Engine: Make: Model: JSX HP: 400				
Odometer Reading: 265,846 ECM Reading: 366,134				
Task	Yes	No		omments
Does the Truck Start?	λ		Jump Start: YES or NO	
Does the motor idle and run normally?	X			
Does the truck have the Emission Deleted?	•	X	"	
Does the Transmission operate in all gears?	\times			
Does the Air load in normal time?	\searrow	á	<u> </u>	
Are there any fluid leaks?		X	OIL or COOLANT	MAJOR or MINOR
Do you see coolant in the oil?		\times		
Is the oil pressure at idle within OEM specs?	\mathcal{L}	J		
Is blow-by present?	<i>→</i>	- 13 11 1	MAJOR or MINOR	
Do you see oil in the coolant?		\times	_	
Pressure check the cooling system	X		PASS or FAIL	
Is the clutch in good operating condition?	7		Rate (1-10):	
Brake Lining: Front R: 70 L: 70 Tag Axle R: L: 1st Axle R: 60 L: 60 2nd Axle R: 40 L: 40 Tire Tread Percentage: Front: 70 Tag Axle: 1st Axle: 30 50 2nd Axle: 50 40				
The fread reflectings. From Tag Axie 1 Axie 1 Axie 1				
Comments:				
Cosmetic Condition: Rate 1 2 3 4 5 6 \$\infty\$ 8 9 10				
Comments: NO CZL				
Other Comments:				

Inspector Print: SAVE KINGAGE,

Date: 5-30-24

Inspector Signature: ____

*** This report is performed as a guide for our buyers. This report is **NOT** a warranty and **DOES NOT** in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way ***